





**Site Details:**

East Street, Rusper

**Client Ref:** GE22977 / PO-8160  
**Report Ref:** GS-QDH-REA-PUI-2QX  
**Grid Ref:** 520779, 137272

**Map Name:** National Grid

**Map date:** 2025

**Scale:** 1:10,000

**Printed at:** 1:10,000



2025




Produced by  
Groundsure Insights  
T: 08444 159000  
E: [info@groundsure.com](mailto:info@groundsure.com)  
W: [www.groundsure.com](http://www.groundsure.com)

© Crown copyright and database rights 2024 Ordnance Survey 100035207

Production date: 15 January 2025

Map legend available at:  
[www.groundsure.com/sites/default/files/groundsure\\_legend.pdf](http://www.groundsure.com/sites/default/files/groundsure_legend.pdf)





## **APPENDIX B**

### **Photographic Record**







Plate 1: Access Path from East Street, Rusper



Plate 2: Access path showing shared access onto site and into adjacent field





Plate 3: Access Gate into the site in the southeast corner



Plate 4: View into site from access gate





Plate 5: Fencing runs along boundary c.1m in height



Plate 6: Adjacent access gate to pathway which runs adjacent to the site





Plate 7: Trough located along eastern boundary



Plate 8: View from east looking west showing mature trees c.15m in height running along the southern boundary





Plate 9: View from the southeast corner looking northwest showing mature trees c.12-15m in height running along the northern boundary



Plate 10: Mature trees c.15m in height along the southern boundary a feed trough is noted





Plate 11: Mature trees along southern boundary



Plate 12: Feed trough along the southern boundary





Plate 13: Southern boundary with East Street showing the boundary fence and signs of tree felling



Plate 14: Timber left from removal of boundary trees





Plate 15: Further timber from tree removal. Southern boundary from the centre of site looking west



Plate 16: View from the centre of site looking east





Plate 17: View from the centre of the site to the northeast corner



Plate 18: Concrete cover present in the centre of the site area





Plate 19: Second concrete cover



Plate 20: Concrete cover, could not be lifted





Plate 21: Third concrete cover could also not be lifted



Plate 22: The western boundary is defined by a residential property with a wooden fence c.1.5m tall





Plate 23: View of the southwestern corner of site, showing the boundary with East Street defined by a hedgerow c.2m in height



Plate 24: View of the northwestern corner of site, showing the northern boundary defined by vegetation and wooden fence. With the western boundary defined by a hedgerow and wooden fence





Plate 25: Northern boundary with mature trees and fencing



Plate 26: Northeast corner of the site





Plate 27: Made Ground Stockpile in the southern centre portion of site



Plate 28: Made Ground in stockpile included brick concrete and wooden fragments among others





Plate 29: Further image of the made ground stockpile showing the materials



Plate 30: A further stockpile of sheeting material





Plate 31: Made ground stockpile looking west



Plate 32: Close-up of potential Asbestos Containing Material (ACM) sheeting





Plate 33: Wider shot of the potential ACM



Plate 34: Wide shot of the two areas of made ground and potential ACM surrounded by mature trees c.15m in height





Plate 35: Further shot of the made ground



Plate 36: Low level vegetation





Plate 37: Area of vegetation in the southern central portion of the field



Plate 38: Southwest corner looking toward the northwest corner





Plate 39: West boundary looking east



Plate 40: Northwest corner looking east





Plate 41: Northern boundary fence



Plate 42: Northern centre of the site looking southeast





Plate 43: North looking south



Plate 44: View of the northeast corner of the site





Plate 45: Northeast corner of the site looking southwest



Plate 46: Northeast corner looking west