

# PULLEN

## ARCHITECTURE

### CONTEXTUAL SITE PHOTOGRAPHS

Renovation and Conversion of Redundant Agricultural Barns

**Tanners Farm Barns**  
Lordings Road · Adversane · Billingshurst  
West Sussex · RH14 9JE

**Doc No: 704-603**  
**Rev: (-) – 18.01.2026**  
**Status: Planning Application Issue**



**View-1 Ariel View of the site (Google)**



**Landscape View looking East**

41-42 Southgate Place, Chichester, West Sussex, PO19 1ET  
T: 01243 859510 E: [office@pullenarchitecture.co.uk](mailto:office@pullenarchitecture.co.uk) W: [www.pullenarchitecture.co.uk](http://www.pullenarchitecture.co.uk)

Pullen Architecture Limited  
A company incorporated in England and Wales under registration number 8734337.  
Registered office: City Gates, 2-4 Southgate, Chichester, West Sussex, PO19 8DJ

## Barn-1

Mid-17th Century threshing barn altered in the C19, including cat-slide bay to its southern end, and later abutting stable wing to the north. There is further evidence to suggest the timber structure has recently been restored along with re-roofing, and a concrete floor.



## Barn-2

19<sup>th</sup> Century former animal shed. A single storey timber frame structure built against the south, east and west masonry walls enclosing the former farmyard. The Front (north) façade is mainly timber with two open central bays. We believe the building evolved with the farmstead when livestock was introduced. This building is in particularly poor condition, structurally unsafe and requires urgent structural attention to prevent collapse, while the clay pantiles have started slipping from the roof.



### Barn-3

Mid-19th Century single storey stable range comprises part timber frame and built against the northern brick/stone wall enclosing the former farmyard, while also abutting the northeastern corner of the former threshing barn. This barn has been subject to various additions and alterations over time.



## Barn-4

Single storey part timber frame/brick structure, believed to be a former open cart barn, with evidence of two open bays facing southwards, albeit currently boarded up. This barn has been subject to recent remedial repairs along with a new roof, albeit using incongruous slates to the pitched roof.

