

Appendix B Field reconnaissance photographs

Site Visit Report

Project name	Thakeham Tiles	Client	Thakeham Tiles Ltd
Document reference	333800445-STN-XX-XX-SVR-GE-0001		
Author / Approver	Emma Judd		
Revision	P01		
Report Date	19 May 2026	Approved	✓

Visit Date	19/05/2026	Weather	Damp, cloudy
-------------------	------------	----------------	--------------

Information

Stantec attended site on the 19th May to visit site and complete a walkover.
Time on site: 11:00-13:00

Summary of Work Activities

Walkover to update Phase 1 Desk Study observations and recommendations.

SITE VISIT PHOTOS



Photograph 1: Overview of yard. Looking south.



Photograph 2: Storage area in central east part of the site. Looking southeast.



Photograph 3: Evidence of previous ground investigation in central east part of site. Looking south.



Photograph 4: Storage areas (pallets at far end) with historical processing infrastructure. Looking east.



Photograph 5: Storage of manufactured paving slabs. Looking west.



Photograph 6: Site overview – storage of blocks. Looking east.



Photograph 7: Access to southern part of the site. Looking north towards where public footpath crosses centre of site.



Photograph 8: Southern part of site – storage/delivery area for raw materials. Looking south.



Photograph 9: Storage of old pallets. Looking east.



Photograph 10: Heavily vegetated areas with mature trees in southeast of site.



Photograph 11: Heavily vegetated areas with mature trees in southeast of site.



Photograph 12: Heavily vegetated areas with mature trees in southeast of site. WS114 pipe shown.



Photograph 13: Scrap metal storage pile. Southeast of site. Looking south.



Photograph 14: Materials storage. Southeast of site. Looking north. BH203 monitoring well shown (raised blue cover).



Photograph 15: Storage of empty AdBlue barrels in southwest of southern materials storage area.



Photograph 16: Heavily vegetated area in south of site. Orange cone covering installation at location WS113. Looking west.



Photograph 17: Heavily vegetated area in south of site with mature trees. Looking south.



Photograph 18: Heavily vegetated area in south of site, with old container. Looking southeast.



Photograph 19: Heavily vegetated area in southwest of site, with mature trees. Looking west, with residential properties beyond.



Photograph 20: Heavily vegetated area in southwest of site – in area of mound (near location of HP102). Looking north.



Photograph 21: Heavily vegetated area in southwest of site – photo taken from top of mound (near location of HP102). Looking southeast.



Photograph 22: Heavily vegetated area in southwest of site – photo taken from materials storage area. Looking west.



Photograph 23: Materials storage area in south of site – stockpiles of raw materials, pallets, scrap metal and used tyres. Looking southeast.



Photograph 24: Overview of materials storage area in south of site – stockpiles of raw materials. Looking south.



Photograph 25: Overview of site from materials storage area in south. Looking north.



Photograph 26: Overview of conveyer from hoppers of raw materials. Looking northwest.



Photograph 27: Conveyor machinery in central west area of site.



Photograph 28: Compressed air generation unit in central west area of site. Looking west.



Photograph 29: Conveyor with residential properties beyond western site boundary in central west area of site. Looking west.



Photograph 30: Building and storage areas, with conveyor, in central area of site. Looking southeast.