




Photograph 31: Public footpath that cuts across central area of site. Looking east.



Photograph 32: Vegetated central western area of site (previously Elizabeth Cottage). Looking west towards residential properties beyond.



Photograph 33: Conveyor infrastructure close to western site boundary. Looking north.



Photograph 34: Overview of central area of site – manufacture, curing and storage of blocks, pavers.
Looking east.



Photograph 35: Building assigned to manufacture of blocks. Looking southeast.



Photograph 36: Fuel storage area with pump. Looking south.



Photograph 37: Heavily vegetated area in west of site, around locations WS205 and WS206 (not visible).
Looking southwest.




Photograph 38: Building on site used for storage. Looking southwest.



Photograph 39: Internal view of building (in area of WS110) on site used for making pavers. Looking west.



Photograph 40: Disused fuel pump. Looking north.



Photograph 41: Internal view of building (in area of WS103) on site used for making pavers. Looking northwest.



Photograph 42: Storage area for distribution in north of site. Looking north.




Photograph 43: Deep borehole (BH1) with continuous datalogger. Looking west.



Photograph 44: Overview of northern part of site. Looking south.



Photograph 45: Entrance to site from Rock Road. Looking west.



Photograph 46: Heavily vegetated area in northwest of site. Looking south from Rock Road.



Photograph 47: Heavily vegetated area in northwest of site.



Photograph 48: Heavily vegetated area in northwest of site.



Photograph 49: Heavily vegetated area in northwest of site. Looking north back towards Rock Road.



Photograph 50: Drainage channel along northwestern site boundary, understood to have been dug by nearby residents (fences visible beyond). Looking northwest.



Photograph 51: Drainage infrastructure in northwestern area of site.



Photograph 52: Drainage infrastructure in northwestern area of site.



Photograph 53: Heavily vegetated area in northwest of site. Looking east.



Photograph 54: Vegetation and drainage ditch in northwestern-most corner of site, at Rock Road.



Photograph 55: Drainage along northern boundary at site entrance from Rock Road.



Photograph 56: Heavily vegetated area in northeast of site. Looking south from Rock Road.



Photograph 57: Heavily vegetated area in northeast of site. Looking along northern boundary with Rock Road.



Photograph 58: Existing site entrance and reception building. Looking south.



Photograph 59: Canteen building in northeastern area of site. Looking northeast.



Photograph 60: Heavily vegetated area in northeast of site. Looking east towards neighbouring residential properties.