Tudor Cottage – SE Elevation for repair and renovation

Including timber framing and masonry infill, failed softwood flush-fitting casements with sealed double-glazed units and weatherboarding.

