

51 Greenacres Existing plans

1. Living Room Bay Window
(Rear View of Property)



2. Bathroom Window (Side View of Property)




Current Windows


White painted wooden single glazed Current windows are rotten – pictures provided. Side view image grey to show frosted glass of bathroom. **No further** difference to proposed windows .



3. Bedroom Window (Front View of Property)



4. Kitchen Window (Side View of Property)



Scale 1:50

0 2.5m 5m



VIEW FULL SIZE

Rear bay window cill has completely degraded to edges and requires immediate replacement.

1. Current Living Room Bay Window



VIEW FULL SIZE

Rot to window. The rotten section measured approx. 12mm in depth.

2. Current Bathroom Window



VIEW FULL SIZE
Flank bathroom window. Silicone seals have begun to lift and there is significant softening/rot to the frames. These require immediate replacement.

2. Current Bathroom Window



VIEW FULL SIZE
Kitchen window with trickle vents to top, silicone seals to sides and brick cill forming drip feature. Some softening present.

4. Current Kitchen Window