CONSTRUCTION PHASE HAZARD IDENTIFICATION
In accordance with the Construction
(Design and Management) Regulations 2015

The hazard sign is a notification to other designers and contractors of foreseeable exceptional risks which could not be fully mitigated or removed by design and are beyond those which could be reasonably expected to be identified by a competent person as defined in the Construction (Design and Management) Regulations 2015.

DRAWING REVIEWED YES OF OU	YES
EXCEPTIONAL RISKS/MITIGATION none or see warning triangle	General Site Wide Operational Risks - Landscape Works 1. DEEP EXCAVATING - COLLAPSE 2. WORKING AT HEIGHT - FALLS/FALLING OBJECTS 3. BURIED SERVICES 4. POSSIBLE SOIL CONTAMINANTS

CLASH WITH TREE ROOTS

CYCLE PARKING

DESIGNATED 1.5M WIDE
CYCLE ROUTE

NEW CYCLE ROUTE
CLASH WITH TREES

CYCLE PARKING

GATE TO BE WIDENED

FIRE TENDER AUTOTRACK

GATE TO BE WIDENED

Play Area

Recreation Ground

TCB

+ 39.7m

El Sub Sta

HILL MEAD

GREENWAY

CHURCHILL AVENUE

THIS DRAWING MUST NOT BE SCALED

CONTRACTOR SHALL CHECK ALL DIMENSIONS ON SITE

NOTES:

1. This drawing should be read in conjunction with all other relevant details, drawings and specifications.
3. All dimensions are to be checked on site before the commencement of works. Any discrepancies are to be reported to the Architect & Engineer for verification. Figured dimensions only are to be taken from this drawing.
   a. The DWG file is issued for the purposes of coordination only and do not represent formal drawing issue and are not to be reprinted in any form. Formal issue of drawings is via DWF, Adobe PDF files and/or hard copies and their associated information issue sheets.
   b. Note that all care has been taken with the export of DWG files and their content, but we recommend that you make due dimensional checks before using any DWG file information. Any errors found are to be reported to MAC Consulting immediately.
4. All levels are shown in metres above Ordnance Datum (m AOD).
5. In the event of any contradiction between this drawing and the specification, then the contractor shall seek clarification from the landscape architect before proceeding.
6. The works on site affect statutory undertakers apparatus, where the contractor is required to verify the location and depth of all such apparatus prior to commencement of work and to take any precautions necessary when working in the vicinity of apparatus.

ACCESS AND CIRCULATION KEY

- GREENWAY ACADEMY SITE BOUNDARY
- FENCELINE
- PEDESTRIAN ROUTE
- ACCESSIBLE ROUTE
- VEHICULAR ROUTE
- CYCLE ROUTE
- COVERED CYCLE PARKING 20 SPACES TOTAL
- PROPOSED UPGRADE FOR DESIGNATED CYCLE ROUTE THROUGH SITE

N

0 15 30 Meters

REV	DESCRIPTION	DATE	DRN	CHK
--	--	--	--	--
--	--	--	--	--
P04	PAVING UPDATED AROUND CANOPY FOR MEWP ACCESS	11/05/2022	MC	MS
P03	CONTRACTOR'S PROPOSALS	11/01/2022	MC	MS
P02	PLANNING ISSUE	22/09/2021	MC	MS
P01	DRAFT CONTRACTORS PROPOSALS	09/07/2021	MC	MS

DRAWING NO.	SRP1029-MAC-XX-XX-D-L-0027
REVISION	P04
DRAWING TITLE	ACCESS AND CIRCULATION STRATEGY
DRAWING SIZE	A1
SCALE	1:500
DATE	20/07/2022
DRAWN BY	MC
CHECKED	MS
STATUS	S4
CLIENT	REDS10
PROJECT	GREENWAY ACADEMY HORSHAM WEST SUSSEX RH12 2JS

GLF TRUST	
SIGNED	
DATE	
DEPARTMENT FOR EDUCATION	
SIGNED	
DATE	

MAC CONSULTING (SCOTLAND) LIMITED
LANDSCAPE · SPORTS · ENVIRONMENT
EDINBURGH
T: 01383741330
E: info@macconsulting-limited.com
W: macconsulting-limited.com

COPYRIGHT © MAC Consulting (Scotland) Limited
Not to be reproduced without written consent of MAC Consulting (Scotland) Limited