

[REDACTED]

From: Mark Christer [REDACTED]
Sent: 18 April 2026 15:28
To: Trees
Subject: Re: DC/26/0354 - Works to Trees Subject to a TPO

[REDACTED] [REDACTED]

Please see map attached

T! - tree is dying according to 3 tree surgeons - Daniel Howick, TreeMarshalls and Alex Newell.
Photo attached.

Planted one hazel 4ft and sapling beech 1ft on same side of drive

T2 large overhanging branch and trunk in ditch leaning towards road. Taking large branch out should give greater longevity to tree and preventing it falling into the utility lines (phone/elec - unsure) or the road

T3 oak with rot at base of trunk. Being guiding by Daniel Howick as we wouldn't have noticed. Concern is roots are in ditch so in autumn/winter has less stability and therefore could fall into road. difficult to show by photo due to location and other bushes and trees growing by it. I have contacted him to see if he is able to state issues for your records.

We have not been succeeded in planting traditional trees along this boundary and have planted an 8ft silver birch and 12 Thuja trees in the last 18 months on our land.