I note further comments on the drawing details provided and would like to provide information to address these.

Justification for a pumped foul discharge into another treatment unit from the new Klargester. - The 20 person Hydroclear HC20 sewage treatment plant provided sufficient capacity for the units which it serves and so there is no requirement for an alternative treatment plant. The Klargester Sigma 5700 litre shallow dig septic tank essentially acts as a holding tank but is no different to having a direct connection from the caravans to the Hydroclear HC20 sewage treatment plant, as such we consider this a suitable proposal.

The location of the pump chamber is shown on the attached updated plan. The pump chamber contains an Ebara Vortex impeller submersible drainage pump with magnetic float, the chamber has an alarm which alerts the owner to a failure of the pump so it can be investigated and rectified.

The Site Drainage Plan incorrectly showed plot 4 draining to both the existing cesspool and the 20 person Hydroclear HC20 sewage treatment plant. This is an error and has now been corrected on the attached. Please note that the site has permission for 6 lawful plots, only the previously approved plots connect to the existing cesspool. All new plots are connected to the Hydroclear HC20 sewage treatment plant.

The 20 person Hydroclear HC20 sewage treatment plant serves 7 pitches. Pitches 3, 5, 6, 7 and 8 each are occupied by 2 people, pitches 9 and 10 are each occupied by 3 and 5 people respectively giving a total occupancy of 18 people meaning that the treatment plant has sufficient capacity.

A chamber with shut-off valve and sampling point is shown on the updated plan to protect water quality in the receiving watercourse should the device/s fail.

Foul drain diameters and gradients are noted on the updated plan as specified in Building Regulations Part H

A Maintenance and Management Plan for the Klargester Sigma 5700 litre shallow dig Septic Tank has been added to the drainage statement.

I hope that the above address the comments and the conditon can now be discharged