




DRY ROT REMOVAL & TREATMENT
Dry rot to be removed and the area treated by specialist company.

FLOOR STRUCTURE
The internal ground floor suspended timber floor structure within this hatched section of the shop has decayed (wet & dry rot present). Floor to be stripped out completely, and a new suspended timber floor installed and supported on the existing steel beams. New padstones to be installed to ends of steel beams.

DRAINAGE PIPEWORK
Defective and leaking soil pipework to be replaced with new clay pipework.

Ordnance Survey, (c) Crown Copyright 2026. All rights reserved. Licence number 100022432

BLOCK PLAN
As Proposed
Scale 1:500



LISTED BUILDING APPLICATION

Status **23.06.2026**
Issued to Planning

Client
Birdhurst Investment Company Ltd

Project
10 MARKET SQUARE HORSHAM:
Remedial works including proposed replacement of the decayed timber floor structure within the commercial unit

Drawing Title
Block Plan As proposed

Scale **1:500** Paper size **A3**

Drawn by **MH** Date **June 2026**

Drawing No. **M215PC/LB/02** Rev.

stuart radley
associates
Chartered Building Surveyors
Unit 5 Tungsten Building,
George Street
Portslade, Brighton BN41 1RA
Tel. 01273 420606
Fax. 01273 420707
e-mail:
info@stuartradleyassociates.co.uk