

- KEY
- ①

All windows to be repaired and decorated to match existing
- ②

Masonry infills required finish to match existing
- ②

Replace louvre with new, colour to match existing

STATUTORY STATUS	
LISTED	NO - BUT LOCALLY LISTED
CONSERVATION	YES

NOTE
This drawing has been prepared from historical information that cannot be guaranteed accurate.
Responsibility is not accepted for errors made by others in scaling from this drawing. All construction information should be taken from figured dimensions only. All dimensions should be checked on site prior to the manufacture of any components. No services should pass through or over the Boxes & Parcels room. No sprinklers to be located in the Comms Room

- HATCHING**
- New Secure Partition wall
- Area not in scope
- New Partition wall
- Book Room Secure wall
- Existing Partition wall
- Structural wall

DATE :

REV

DRAWN

CHECKED

NOTES



Boleyn House,
St Augustine's Business Park,
Whitstable
CT5 2QJ

Tel 01227 281 000
info@morrisandspottiswood.co.uk

Project

HORSHAM CARFAX

1-2 CARFAX, HORSHAM,
WEST SUSSEX
RH12 1DN
PIM No.10352

BARCLAYS

Drawing Title

REAR ELEVATION

AS PROPOSED

MAYOR BRANCH REFURBISHMENT 2026

Branch Sort Code	Branch ID	Supplier Project No	
20-42-58	00	RMWBS10200	
Scale	Drawn	Checked	Date
1:100@A3	JNA	—	03/11/2025
Drg.No	RMWBS10200_033		Revision
			/
Architectural Practice: MORRIS & SPOTTISWOOD			



FULL SCHEME DESIGN

CONFIDENTIAL