

GROUND FLOOR





Heat pump position fails noise assessment and on boundary. Planning required.


Consumer board may need to be upgraded.

Submain located on external wall. Submain cable to run at low level to corner then up to soffit.

D2 is to run behind toilet and bath to enter soil pipe.

Submain cable to enter through soffit, span across loft, T into cylinder and follow primaries out to cylinder.

FIRST FLOOR



Primaries enter through soffit, span across loft and and down to airing cupboard.

HWC going in place of existing system. All connections available.

Landing heat loss covered by entrance hall.