

Telephone cable is going through the tree's canopy.
Tree canopy overhanging neighbouring driveway, partially covering front of property and are lower than pedestrian head height.