Please accept this email as confirmation that the new lighting columns have now been installed to the hardstanding area exactly in accordance with the lighting design reference 250285-LTBL-REP-001_P1_Lighting Assessment. All excavation works were overseen by the arboricultural consultant & completed to his satisfaction.

If you have any questions regarding the above or require any further information, please do not hesitate to get in touch.

Kind regards

Dan Argles
Contracts Manager
T: 01798 872555 **M:** 07551 153947
E: dana@landbuild.co.uk

LANDBUILD

www.landbuild.co.uk Landbuild Ltd The Colonnades, London Road, Pulborough, West Sussex RH20 1AS



Instagram: landbuildltd Linkedin: landbuild-ltd

Constructionline Gold Member
Achilles BuildingConfidence Advanced Member
Smas Registered
veriforce CHAS Compliant Contractor
ISO 9001 ISOQAR UKAS MANAGEMENT SYSTEMS 0026
ISO 14001 ISOQAR UKAS MANAGEMENT SYSTEMS 0026
ISO 45001 ISOQAR UKAS MANAGEMENT SYSTEMS 0026