Root pruning

Excavations are to be undertaken within the RPAs of retained trees in order to facilitate the installation of retaining walls. All excavation within the RPAs are to be undertaken by hand to a minimum depth of 600mm deep. Soil will be lowered with the aid of an open. Are no greater than the soil depth of the proposed wall and the spoil removed with the aid of a shovel. During the excavation there are to be no unprotected roots are to be covered over with a minimum of two layers of damp hessian to prevent drying out, and where necessary be sheltered to prevent cold/ice or contamination.

'No Dig' Surfacing

Trees can be affected by construction within the RPAs either through the direct damage caused by the removal of roots, compaction of the rooting environment or secondary damage such as poisoning through leaks and spills (oils, fuels, etc.) or through de-icing (road salt, etc.).

Proposed hard surfacing within the RPAs of retained trees is to be designed so that it can be situated above the existing soil level and to minimise any adverse impact upon the tree RPAs, as the use of traditional foundations can result in excessive root loss through direct removal of roots during excavation by compaction of the soil beneath the excavation, as such this 'traditional' type of foundation should be avoided.

Where designing hard surfacing that is to be situated within RPAs, the design team need to pay particular attention to the proposed usage (pedestrian, domestic traffic, delivery vans, Emergency vehicles, HGVs etc.). the existing and proposed levels of hard surfacing and finished floor levels, edging types and details, porosity to free trunks and surface rooting, construction depths, SUDs, etc.

Possible sub-bases foundations system(s) by hard surfacing surfaces within the RPAs of retained trees could include:

- A proprietary system such as a multi-dimensional confinement system (Cellweb TRP or similar).
- Engineered solution such as a road deck, bridge, etc.

An engineered solution is likely require a level of excavation for sub base and a suitable foundation can be designed a wood roots and for the installation the structure.

Trees can be affected by construction within the RPAs either through the direct damage caused by the removal of roots, compaction of the rooting environment or secondary damage such as poisoning through leaks and spills (oils, fuels, etc.) or through de-icing (road salt, etc.).

Where it is required by the hard surfacing is to be removed and or re-levied within the RPAs of retained trees it is to be undertaken under direct on-site arboricultural supervision, during the landscaping phase of the development.

The levering course will be broken up using a handheld pneumatic breaker, hand tools and redepthness to break up and remove the underlayment using a bob to loosen the material and moved using shovels and wheelbarrows.

In some instances, and at the discretion of the arborist a may be possible to use an excavator using a hydraulic breaker and a suitably sized toothless grasping bucket. a an excavator is to be used it must be situated outside of the RPAs or from ground protecting.

Where hand RPAs or from ground protecting.

Wheelbarrow systems is used bwire a to be **NO** disturbance of the soil beneath. If bed of either sharp sand, wood chip or topsoil will be applied as soon as practicably possibe to prevent desiccation.

Utility apparatus


Underground utility apparatus

Maintenance trenching of the installation of underground apparatus are to be undertaken in a way that avoiding affects the health of the tree. For this reason, particular care should be taken in the root and methods of installation of all underground apparatus. Wherever possible, apparatus should be routed outside of RPAs. Where this is not possible, it is preferable to keep apparatus together in common route. All apparatus chambers should be sited outside of the RPAs.

Where underground apparatus is to pass within the RPAs, detailed plans showing the proposed route should be drawn up in conjunction with the project arboriculturist. In such cases trenchless retention can be retained, and protected excavations should be undertaken using hand tools (un-spade, fork, shovels) or a combination of hand tools (un-spade, fork, shovels) or a combination of trenchless and manual excavation (vacuum excit).

Above-ground utility apparatus

Above-ground apparatus(including CCTV cameras and lighting) should be sited to avoid the need for directional tree pruning, as such the current and future crown size of the tree should be assessed. Tree branches can be pruned back with care to provide space. Though it is not appropriate to undertake any significant pruning works to trees. Any pruning should be undertaken in accordance with BS3998:2010



indicative only

Arboricultural Impacts

Impacts	Nos. of trees
Trees to be removed	9
Groups / hedges to be removed (Partial removal of groups)	3 (G)
Groups / hedges with proposed incursions into RPAs	4
Trees with proposed incursions into RPAs	7
Groups / hedges with proposed incursions into RPAs	4
Trees that will require pruning	0
Trees to be transplanted	1
Groups / hedges that will require pruning	0
Groups / hedges to be transplanted	0

No.	Species	Proposed structure	Incursion
T13	Crab apple	Tiered cobweb	RPA
T15	Cherry	Maypng wall	RPA
T32	London Plane	Hard surfacing	RPA
T36	Leylend Cypress	Hard surfacing	RPA
T37	Silver maple	Hard surfacing	RPA
T42	Wild Cherry	Maypng wall	RPA
T45	Wild Cherry	Maypng wall	RPA
G22	Lombardy Poplar	Hard surfacing	RPA
G27	Viburnus	Hard surfacing	RPA
G29	Viburnus	Fencing	RPA
G37	Common Lime	Hard surfacing	RPA

Arboricultural Impacts - RPAs (Area)

No.	Species	RPA (m²)	Incursion (%)
T13	Crab apple	20.9	4.2 20.1
T15	Cherry	716.6	24.6 6.9
T32	London Plane	772.0	113.7 14.1
T36	Leylend Cypress	772.0	24.8 13.8
T37	Silver maple	298.5	48.8 16.9
T42	Wild Cherry	42.1	4.7 11.2
T45	Wild Cherry	306	0.3 1.0
G22	Lombardy Poplar	398.7	62.1 13.6
G27	Viburnus	113.1	5.5 4.9
G29	Viburnus	40.7	Negligible N/A
G37	Common Lime	443.4	61.2 13.8

Tree Work Schedule

No.	Species	Works	Category
T03	Common Ivy	Fell to ground level and grind stump.	C1
T04	Cherry	Fell to ground level and grind stump.	C1
T05	Cherry	Fell to ground level and grind stump.	C1
T09	Common or Black Elderberry	Fell to ground level and grind stump. Trim to be a formal/neat shape prune of crown may be necessary to facilitate movement.	B1
T10	Common Ivy	Fell to ground level and grind stump. Work prune of crown may be necessary	C1
T11	Cherry	Fell to ground level and grind stump.	U
T14	Crab apple	Fell to ground level and grind stump.	C1
T31	English Elm	Fell to ground level and grind stump.	U
T41	Cherry	Fell to ground level and grind stump.	B1
G06	Viburnus	Fell to ground level and grind stumps.	B2
G16	Viburnus	Fell to ground level and grind stumps.	C2
H1	A Hedge	Fell to ground level and grind stumps.	C2

All tree work is to be undertaken in accordance with British Standard BS 3998 2010 Tree work - Recommendations.

All arisings are to be removed and be left as tidy as is found. Care is to be taken to be removed and be left as tidy as is found. Care is to be taken to the ground around retained trees to make sure that it does not become compacted as a result of tree surgery operations. No equipment or vehicles such as timber lorries, tractors, excavators or cranes shall be parked or driven beneath the crowns of any retained trees, to prevent subsequent damage and root death.

No. of individual trees to be removed

U	A	B	C
2	0	2	5

No. of groups / hedges to be removed


U	A	B	C
0 (0)	0 (0)	1 (0)	2 (0)

() = Partial removal of a groups

Arboricultural Method Statement

All tree work is to be undertaken in accordance with British Standard BS 3998 2010 Please refer to Arbtech Consulting Ltd. Tree Schedule, Arboricultural Method Statement and Tree Protection Plan. for full details of all surveyed trees and how all aspects of the development may/be implemented without detriment to retained trees.

Sheet Layout



indicative only

Key:			
Tree No.:	T01	Tree Categories	Thumbs:
RPAs:		Category 'A' Trees:	Category 'A' groups
		Category 'B' groups:	Category 'B' Trees
		Category 'C' groups	Category 'C' Trees
Category 'U' groups		Category 'U' trees:	Trees to be removed T03
Existing Gate		Proposed Site Plan:	Vegetation - Boundaries
Vegetation - Hard surfacing		Vegetation - Fences:	

All tree work is to be undertaken in accordance with British Standard BS 3998 2010 Please refer to Arbtech Consulting Ltd. Tree Schedule, Arboricultural Method Statement and Tree Protection Plan. for full details of all surveyed trees and how all aspects of the development may/be implemented without detriment to retained trees.

Sheet Layout

indicative only

Key:			
Tree No.:	T01	Tree Categories	Thumbs:
RPAs:		Category 'A' trees:	Category 'A' groups
		Category 'B' groups:	Category 'B' trees
Category 'C' groups		Category 'U' trees:	Trees to be removed T03
Existing Gate		Proposed Site Plan:	Vegetation - Boundaries
Vegetation - Hard surfacing		Vegetation - Fences:	

Unit 3, Well House Barns, Chester. CH4 0DH
https://arbtech.co.uk, 01244 661 170

Project:
Steyning Grammar School,
Shooting Field,
Steyning,
BN44 3RX

Client:
DFE/ Steyning Grammar Shooting Upper School

Drawing:
Arboricultural Impact Assessment

Based on:
SRP1121-WWA-00-EX-D-L-1970 P09

Drawing No:
SRP1121-ACL-XX-XX-D-O-0003

Sheet:
Overview

Date:
Feb 2026

Scale:
1:1000 @ A0

Drawn:
FG

© Arbtech Consulting Ltd 2026