Treeline™ Services Ltd.
---------- Tree Health Care Specialists ----------

Chadhurst Farm
Coldharbour Lane
Dorking, Surrey RH4 3JH

Tel: 01306 741800
Fax: 01306 885150
Email: office@treeline.co.uk
www.treeline.co.uk

Client:

Ms. Sarah Chamberlain
Firstport Group Limited
Marlborough House
Wigmore Place
Wigmore Lane
Luton
LU2 9EX

Our Ref: 48918

Date: 10/9/2024

Site Address: Oaklands Estate, Brabry Drive, Horsham, West Sussex

We have been instructed by our client to carry out the following arboricultural operations at the above site address.

Please see below the specification, reasons and location plan for this application.

Our contact details are as follows: Treeline Services Ltd., Chadhurst Farm, Coldharbour Lane, Dorking, Surrey RH4 3JH. Telephone: 01306 741800

Or reply by Email to office@treeline.co.uk

Yours sincerely

Lisa Llewellyn

VAT Registration No 800 9964 23

Treeline Services Ltd. Registered Address - Chadhurst Farm
Coldharbour Lane, Dorking, Surrey RH4 3JH
Registered in England & Wales Number 4615608

Map Ref.	Species	Location	Work Specification	Our Ref: 48918

			Priority 2
019	Oak	As Per Map	Carry Out Resistograph Report To Ascertain Levels Of Decay Within The Main Stem, Carry Out A Climbing Inspection Of All Previous Failure Points, Cavities And Unions. Remove Deadwood Greater Than 25mm In Diameter. Crown Lift To A Height Of 2.5m From Ground Level
035	Oak	As Per Map	Crown Lift To A Height Of 6m Over Road, Remove Deadwood 25mm And Greater In Diameter, Sever & Remove A Section Of Ivy From Ground Level To A Height Of 1m Using Hand Tools Only Re-inspect Base.
037	Sycamore	As Per Map	Crown Lift To A Height Of 6m Over Road, And 2.5m From Ground Level Over Site, Sever And Remove A Section Of Ivy From Ground Level To A Height Of 1m Using Hand Tools Only, Re-inspect Base
038	Sycamore	As Per Map	Sever And Remove A Section Of Ivy From Ground Level To A Height Of 1m Using Hand Tools Only
039	Oak	As Per Map	Sever And Remove A Section Of Ivy From Ground Level To A Height Of 1m Using Hand Tools Only Remove Deadwood Greater Than 25mm In Diameter.
047	Sycamore	As Per Map	Carefully Fell To Near Ground Level.
050	Elm Group	As Per Map	Carefully Fell Deceased Tree To Near Ground Level
			It Is Company Policy To Do A Free Enquiry With The Local Planning Department To Rule Out Tree Restrictions If The Above Work Is Accepted.

TREE NO.	**APPLICATION REASONS**	Our Ref: 48918
019	Crown lift To give sufficient height clearance over the lawn area under the crown Removal of deadwood To reduce the volume of debris falling from crown over the target area and reduce risk of injury. The remainder of the works specified are	

	exempt of application but are further exploratory investigative works to further assess the condition.
047	This is a deceased tree within falling distance of the public foot path and bin store area of the site, felling to near ground level to remove risk of failure and remove risk of injury and or damage give the location and target area.
050	This is two trees, a deceased tree and a tree 50% deceased tree within falling distance of the public foot path area of the site and public road, felling to near ground level to remove risk of failure and remove risk of injury and or damage give the location and target area.

SITE MAP


Our Ref: 48918

Ms. Sarah Chamberlain
Firstport Group Limited
Marlborough House
Wigmore Place
Wigmore Lane
Luton

LU2 9EX

Site Address: Oaklands Estate, Brabry Drive, Horsham, West Sussex

Council: Horsham District Council



Contains OS data © Crown copyright and database right 2018

PICTURES

Job No: 48918

Photo 1

Photo 2

Photo 3

Photo 4

VAT Registration No 800 9964 23

Treeline Services Ltd. Registered Address - Chadhurst Farm
Coldharbour Lane, Dorking, Surrey RH4 3JH
Registered in England & Wales Number 4615608