
Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/19/2026 - PI01X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
18	Upstream	PI01X	J-07955	-



1, 00:00:00, 0.00 m
Start node, catchpit, reference: S135



2, 00:00:24, 1.65 m
Finish node, other special chamber, reference: PI01, PUMP TANK

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
19	1	19/09/26	12:43	J-07955	No Rain Or Snow	Yes	S135X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S135
Road:	Platts Corner	**Inspected Length:**	0.78 m	**Upstream Pipe Depth:**	1.600 m
Location:	Footway	**Total Length:**	0.78 m	**Downstream Node:**	AQUACELL
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	375 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	CP	Start node, catchpit, reference: S135	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.78	SKF	Finish node, soakaway, reference: AQUACELL	00:00:17		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/19/2026 - S135X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
19	Downstream	S135X	J-07955	-



1, 00:00:00, 0.00 m
Start node, catchpit, reference: S135



2, 00:00:17, 0.78 m
Finish node, soakaway, reference: AQUACELL

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
20	1	19/09/26	14:39	J-07955	No Rain Or Snow	Yes	S102X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S102
Road:	Platts Corner	**Inspected Length:**	40.54 m	**Upstream Pipe Depth:**	1.021 m
Location:	Footway	**Total Length:**	40.54 m	**Downstream Node:**	S103
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.276 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:351



Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.28 m **S103**					
0.00	IC	Start node, inspection chamber, reference: S103	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
40.54	ICF	Finish node, inspection chamber, reference: S102	00:04:28		
S102 **Depth: 1.02 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/19/2026 - S102X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
20	Upstream	S102X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S103



2, 00:04:28, 40.54 m
Finish node, inspection chamber, reference: S102



3, 00:04:28, 40.54 m
Finish node, inspection chamber, reference: S102

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
21	1	19/09/26	14:47	J-07955	No Rain Or Snow	Yes	S101X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S101
Road:	Platts Corner	**Inspected Length:**	41.29 m	**Upstream Pipe Depth:**	0.800 m
Location:	Footway	**Total Length:**	41.29 m	**Downstream Node:**	S102
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.276 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:358



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S102	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
26.63	CN	Connection other than junction at 3 o'clock, 100mm dia	00:04:13		
41.29	ICF	Finish node, inspection chamber, reference: S101	00:06:43		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/19/2026 - S101X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
21	Upstream	S101X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S102



2, 00:06:43, 41.29 m
Finish node, inspection chamber, reference: S101

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
22	2	08/10/26	13:46	J-07955	No Rain Or Snow	Yes	S106X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S106
Road:	Platts Corner	**Inspected Length:**	33.49 m	**Upstream Pipe Depth:**	1.021 m
Location:	Footway	**Total Length:**	34.48 m	**Downstream Node:**	S107
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.489 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post rehab inspection	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:299



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S107	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
2.86	JN	Junction at 2 o'clock, 150mm dia	00:00:19		
4.36	RPT	Point repair, localised lining of connection from 12 o'clock to 12 o'clock	00:00:32		
19.80	JN	Junction at 2 o'clock, 150mm dia	00:02:16		
33.49	MHF	Finish node, manhole, reference: S106	00:03:34		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - S106X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
22	Upstream	S106X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S107



2, 00:00:32, 4.36 m
Point repair, localised lining of connection from 12 o'clock to 12 o'clock



3, 00:03:34, 33.49 m
Finish node, manhole, reference: S106

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
23	1	20/09/26	8:31	J-07955	No Rain Or Snow	Yes	S105X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F105
Road:	Platts Corner	**Inspected Length:**	31.67 m	**Upstream Pipe Depth:**	0.801 m
Location:	Footway	**Total Length:**	31.67 m	**Downstream Node:**	S106
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.021 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:275




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S106	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
2.30	CN	Connection other than junction at 3 o'clock, 100mm dia	00:00:20		
21.37	CN	Connection other than junction at 3 o'clock, 100mm dia	00:02:05		
31.67	ICF	Finish node, inspection chamber, reference: S105	00:03:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S105X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
23	Upstream	S105X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S106



2, 00:03:23, 31.67 m
Finish node, inspection chamber, reference: S105



3, 00:03:23, 31.67 m
Finish node, inspection chamber, reference: S105

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
24	1	20/09/26	8:47	J-07955	No Rain Or Snow	Yes	S107X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S107
Road:	Platts Corner	**Inspected Length:**	11.25 m	**Upstream Pipe Depth:**	1.489 m
Location:	Footway	**Total Length:**	11.25 m	**Downstream Node:**	S110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.562 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVY COMPLETE
Recommendations:

Scale: 1:98




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S107	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
1.42	LL	Line deviates left	00:00:14		
11.25	CPF	Finish node, catchpit, reference: S110	00:01:13		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S107X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
24	Downstream	S107X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S107



2, 00:01:13, 11.25 m
Finish node, catchpit, reference: S110



3, 00:01:13, 11.25 m
Finish node, catchpit, reference: S110

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
25	1	20/09/26	9:12	J-07955	No Rain Or Snow	Yes	RWP01X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	RWP01
Road:	Platts Corner	**Inspected Length:**	2.09 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	2.09 m	**Downstream Node:**	S108
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
2.09	CN	Connection other than junction at 10 o'clock, 90mm dia	00:00:34		
2.09	OCF	Finish node, other special chamber, reference: RWP01: RAIN WATER PIPE	00:00:34		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - RWP01X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
25	Upstream	RWP01X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S108



2, 00:00:34, 2.09 m
Finish node, other special chamber, reference: RWP01, RAIN WATER PIPE

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
26	1	20/09/26	9:15	J-07955	No Rain Or Snow	Yes	S108X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S108
Road:	Platts Corner	**Inspected Length:**	13.62 m	**Upstream Pipe Depth:**	1.200 m
Location:	Footway	**Total Length:**	13.62 m	**Downstream Node:**	S109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.285 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:118



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
13.29	LR	Line deviates right	00:00:38		
13.62	ICF	Finish node, inspection chamber, reference: S109	00:00:41		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S108X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
26	Downstream	S108X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S108



2, 00:00:41, 13.62 m
Finish node, inspection chamber, reference: S109

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
27	1	20/09/26	9:17	J-07955	No Rain Or Snow	Yes	S109X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S109
Road:	Platts Corner	**Inspected Length:**	11.61 m	**Upstream Pipe Depth:**	1.285 m
Location:	Footway	**Total Length:**	11.61 m	**Downstream Node:**	S110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.562 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:101




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S109	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.55	LR	Line deviates right	00:00:07		
11.15	LR	Line deviates right	00:01:05		
11.61	CPF	Finish node, catchpit, reference: S110	00:01:11		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S109X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
27	Downstream	S109X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S109



2, 00:01:11, 11.61 m
Finish node, catchpit, reference: S110

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
28	1	20/09/26	9:25	J-07955	No Rain Or Snow	Yes	RWP02X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	RWP02
Road:	Platts Corner	**Inspected Length:**	4.39 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	4.39 m	**Downstream Node:**	S109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S109	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.66	LL	Line deviates left	00:00:06		
1.32	LR	Line deviates right	00:00:08		
4.39	OCF	Finish node, other special chamber, reference: RWP02: RAIN WATER PIPE	00:00:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - RWP02X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
28	Upstream	RWP02X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S109



2, 00:00:23, 4.39 m
Finish node, other special chamber, reference: RWP02, RAIN WATER PIPE

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
29	2	08/10/26	12:16	J-07955	No Rain Or Snow	Yes	S110X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S110
Road:	Platts Corner	**Inspected Length:**	4.94 m	**Upstream Pipe Depth:**	1.562 m
Location:	Footway	**Total Length:**	4.94 m	**Downstream Node:**	S111
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.290 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post rehab inspection	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S111	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.55	LR	Line deviates right	00:00:05		
3.84	RPR	Point repair, pipe replaced from 12 o'clock to 12 o'clock	00:00:19		
4.94	CPF	Finish node, catchpit, reference: S110	00:00:33		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - S110X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
29	Upstream	S110X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S111



2, 00:00:19, 3.84 m
Point repair, pipe replaced from 12 o'clock to 12 o'clock



3, 00:00:33, 4.94 m
Finish node, catchpit, reference: S110

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
30	1	20/09/26	9:34	J-07955	No Rain Or Snow	Yes	S111X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S111
Road:	Platts Corner	**Inspected Length:**	9.23 m	**Upstream Pipe Depth:**	1.290 m
Location:	Footway	**Total Length:**	9.23 m	**Downstream Node:**	S112
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.195 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:80



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S111	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
1.76	LL	Line deviates left	00:00:09		
9.23	MHF	Finish node, manhole, reference: S112	00:00:29		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S111X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
30	Downstream	S111X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S111



2, 00:00:29, 9.23 m
Finish node, manhole, reference: S112

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
31	1	20/09/26	9:44	J-07955	No Rain Or Snow	Yes	S110Y

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S110
Road:	Platts Corner	**Inspected Length:**	2.31 m	**Upstream Pipe Depth:**	1.562 m
Location:	Footway	**Total Length:**	2.31 m	**Downstream Node:**	RWHT
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S110	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
2.31	OCF	Finish node, other special chamber, reference: RWHT: RAIN WATER HOLDING TANK	00:00:32		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S110Y

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
31	Downstream	S110Y	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S110



2, 00:00:32, 2.31 m
Finish node, other special chamber, reference: RWHT, RAIN WATER HOLDING TANK

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
32	1	20/09/26	10:03	J-07955	No Rain Or Snow	Yes	S103X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S103
Road:	Platts Corner	**Inspected Length:**	27.53 m	**Upstream Pipe Depth:**	1.276 m
Location:	Footway	**Total Length:**	27.53 m	**Downstream Node:**	S104
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.427 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:239



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S104	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
26.50	LR	Line deviates right	00:01:49		
27.30	LR	Line deviates right	00:01:56		
27.53	ICF	Finish node, inspection chamber, reference: S103	00:02:14		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S103X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
32	Upstream	S103X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S104



2, 00:02:14, 27.53 m
Finish node, inspection chamber, reference: S103

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
33	1	20/09/26	10:20	J-07955	No Rain Or Snow	Yes	S104X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S104
Road:	Platts Corner	**Inspected Length:**	5.05 m	**Upstream Pipe Depth:**	1.427 m
Location:	Footway	**Total Length:**	5.05 m	**Downstream Node:**	S113
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.455 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S113	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.05	ICF	Finish node, inspection chamber, reference: S104	00:00:31		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S104X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
33	Upstream	S104X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S113



2, 00:00:31, 5.05 m
Finish node, inspection chamber, reference: S104

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
34	1	20/09/26	10:21	J-07955	No Rain Or Snow	Yes	RWHTX


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	RWHT
Road:	Platts Corner	**Inspected Length:**	2.85 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	2.85 m	**Downstream Node:**	S113
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.455 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S113	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
2.85	OCF	Finish node, other special chamber, reference: RWHT: RAIN WATER HOLDING TANK	00:00:18		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - RWHTX

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
34	Upstream	RWHTX	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S113



2, 00:00:18, 2.85 m
Finish node, other special chamber, reference: RWHT, RAIN WATER HOLDING TANK

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
35	1	20/09/26	10:23	J-07955	No Rain Or Snow	Yes	S112X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S112
Road:	Platts Corner	**Inspected Length:**	5.71 m	**Upstream Pipe Depth:**	1.195 m
Location:	Footway	**Total Length:**	5.71 m	**Downstream Node:**	S113
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.445 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S113	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
5.16	LR	Line deviates right	00:00:33		
5.71	ICF	Finish node, inspection chamber, reference: MHF	00:00:37		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S112X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
35	Upstream	S112X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S113



2, 00:00:37, 5.71 m
Finish node, inspection chamber, reference: MHF

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
36	1	20/09/26	10:56	J-07955	No Rain Or Snow	Yes	S113X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S113
Road:	Platts Corner	**Inspected Length:**	12.09 m	**Upstream Pipe Depth:**	1.445 m
Location:	Footway	**Total Length:**	12.09 m	**Downstream Node:**	S119
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.551 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:105



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S113	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
12.09	MHF	Finish node, manhole, reference: S119	00:00:53		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S113X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
36	Downstream	S113X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S113



2, 00:00:53, 12.09 m
Finish node, manhole, reference: S119

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
37	1	20/09/26	11:03	J-07955	No Rain Or Snow	Yes	OB1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	OB1
Road:	Platts Corner	**Inspected Length:**	4.72 m	**Upstream Pipe Depth:**	0.460 m
Location:	Footway	**Total Length:**	4.72 m	**Downstream Node:**	S120
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.161 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S120	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.72	GYF	Finish node, gully, reference: OB1	00:00:39		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
37	Upstream	OB1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S120



2, 00:00:39, 4.72 m
Finish node, gully, reference: OB1

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
38	1	20/09/26	11:08	J-07955	No Rain Or Snow	Yes	S120X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S120
Road:	Platts Corner	**Inspected Length:**	13.74 m	**Upstream Pipe Depth:**	1.161 m
Location:	Footway	**Total Length:**	13.74 m	**Downstream Node:**	S122
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.175 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:119




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S120	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
13.74	MHF	Finish node, manhole, reference: S122	00:00:47		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S120X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
38	Downstream	S120X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S120



2, 00:00:47, 13.74 m
Finish node, manhole, reference: S122

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
39	1	20/09/26	11:17	J-07955	No Rain Or Snow	Yes	RWP03X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	RWP03
Road:	Platts Corner	**Inspected Length:**	6.15 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	6.15 m	**Downstream Node:**	S118
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.546 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:54




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S118	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
6.15	OCF	Finish node, other special chamber, reference: RWP03: RAIN WATER PIPE	00:01:02		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - RWP03X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
39	Upstream	RWP03X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S118



2, 00:01:02, 6.15 m
Finish node, other special chamber, reference: RWP03, RAIN WATER PIPE

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
40	1	20/09/26	11:21	J-07955	No Rain Or Snow	Yes	S117X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S117
Road:	Platts Corner	**Inspected Length:**	17.97 m	**Upstream Pipe Depth:**	1.496 m
Location:	Footway	**Total Length:**	17.97 m	**Downstream Node:**	S118
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.546 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	300 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:156



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S118	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.83	JN	Junction at 2 o'clock, 100mm dia	00:00:23		
17.97	ICF	Finish node, inspection chamber, reference: S117	00:01:00		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S117X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
40	Upstream	S117X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S118



2, 00:01:00, 17.97 m
Finish node, inspection chamber, reference: S117

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
41	1	20/09/26	11:25	J-07955	No Rain Or Snow	Yes	S118X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S118
Road:	Platts Corner	**Inspected Length:**	17.38 m	**Upstream Pipe Depth:**	1.546 m
Location:	Footway	**Total Length:**	17.38 m	**Downstream Node:**	S119
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.551 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	300 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:151


Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: 1.55 m			
		S118			
0.00	IC	Start node, inspection chamber, reference: S118	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
17.38	MHF	Finish node, manhole, reference: S119	00:01:06		
		S119			
		Depth: 1.55 m			

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S118X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
41	Downstream	S118X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S118



2, 00:01:06, 17.38 m
Finish node, manhole, reference: S119

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
42	1	20/09/26	11:30	J-07955	No Rain Or Snow	Yes	OB2X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	OB2
Road:	Platts Corner	**Inspected Length:**	4.61 m	**Upstream Pipe Depth:**	0.480 m
Location:	Footway	**Total Length:**	4.61 m	**Downstream Node:**	S122
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.175 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S122	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.61	LR	Line deviates right	00:00:26		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
42	Upstream	OB2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S122



2, 00:00:26, 4.61 m
Line deviates right

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
43	1	20/09/26	11:35	J-07955	No Rain Or Snow	Yes	S121X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	Not Specified	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S121
Road:	Platts Corner	**Inspected Length:**	11.87 m	**Upstream Pipe Depth:**	1.200 m
Location:	Footway	**Total Length:**	11.87 m	**Downstream Node:**	S122
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.175 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	300 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments:
Recommendations:

Scale: 1:103




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S122	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
11.87	MHF	Finish node, manhole, reference: S121	00:00:45		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S121X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
43	Upstream	S121X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S122



2, 00:00:45, 11.87 m
Finish node, manhole, reference: S121

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
44	1	20/09/26	11:37	J-07955	No Rain Or Snow	Yes	S122X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S122
Road:	Platts Corner	**Inspected Length:**	5.71 m	**Upstream Pipe Depth:**	1.175 m
Location:	Footway	**Total Length:**	5.71 m	**Downstream Node:**	S123
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.797 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	300 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S122	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.71	MHF	Finish node, manhole, reference: S123	00:00:24		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S122X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
44	Downstream	S122X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S122



2, 00:00:24, 5.71 m
Finish node, manhole, reference: S123

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
45	1	20/09/26	11:41	J-07955	No Rain Or Snow	Yes	S119X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S119
Road:	Platts Corner	**Inspected Length:**	9.56 m	**Upstream Pipe Depth:**	1.175 m
Location:	Footway	**Total Length:**	9.56 m	**Downstream Node:**	S124
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.797 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:83




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S119	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:03		
9.56	MHF	Finish node, manhole, reference: S124	00:00:31		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S119X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
45	Downstream	S119X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S119



2, 00:00:31, 9.56 m
Finish node, manhole, reference: S124

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
46	1	20/09/26	12:36	J-07955	No Rain Or Snow	Yes	GY01X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	GY01
Road:	Platts Corner	**Inspected Length:**	5.71 m	**Upstream Pipe Depth:**	0.440 m
Location:	Footway	**Total Length:**	5.71 m	**Downstream Node:**	S121
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S121	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.71	GYF	Finish node, gully, reference: GY01	00:00:35		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - GY01X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
46	Upstream	GY01X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S121



2, 00:00:35, 5.71 m
Finish node, gully, reference: GY01

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
47	1	20/09/26	12:37	J-07955	No Rain Or Snow	Yes	GY02X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	GY02
Road:	Platts Corner	**Inspected Length:**	11.98 m	**Upstream Pipe Depth:**	0.400 m
Location:	Footway	**Total Length:**	11.98 m	**Downstream Node:**	S121
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:104




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: MH	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
9.56	LL	Line deviates left	00:00:24		
11.98	GYF	Finish node, gully, reference: GY02	00:00:33		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - GY02X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
47	Upstream	GY02X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: MH



2, 00:00:33, 11.98 m
Finish node, gully, reference: GY02

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
48	1	20/09/26	12:39	J-07955	No Rain Or Snow	Yes	GY03X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	GY03
Road:	Platts Corner	**Inspected Length:**	5.49 m	**Upstream Pipe Depth:**	0.400 m
Location:	Footway	**Total Length:**	5.49 m	**Downstream Node:**	S121
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S121	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.49	GYF	Finish node, gully, reference: GY03	00:00:21		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - GY03X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
48	Upstream	GY03X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S121



2, 00:00:21, 5.49 m
Finish node, gully, reference: GY03

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
49	1	20/09/26	12:41	J-07955	No Rain Or Snow	Yes	GY04X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	GY04
Road:	Platts Corner	**Inspected Length:**	4.94 m	**Upstream Pipe Depth:**	0.400 m
Location:	Footway	**Total Length:**	4.94 m	**Downstream Node:**	S121
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S121	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
4.94	GYF	Finish node, gully, reference: GY04	00:00:35		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - GY04X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
49	Upstream	GY04X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S121



2, 00:00:35, 4.94 m
Finish node, gully, reference: GY04

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
50	1	20/09/26	12:58	J-07955	No Rain Or Snow	Yes	OB4X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	OB4
Road:	Platts Corner	**Inspected Length:**	6.92 m	**Upstream Pipe Depth:**	0.350 m
Location:	Footway	**Total Length:**	6.92 m	**Downstream Node:**	S123
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.797 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:60




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S123	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
6.92	GYF	Finish node, gully, reference: OB4	00:00:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB4X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
50	Upstream	OB4X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S123



2, 00:00:23, 6.92 m
Finish node, gully, reference: OB4

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
51	1	20/09/26	13:01	J-07955	No Rain Or Snow	Yes	S123X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S123
Road:	Platts Corner	**Inspected Length:**	0.77 m	**Upstream Pipe Depth:**	1.797 m
Location:	Footway	**Total Length:**	0.77 m	**Downstream Node:**	PI02
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S123	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.77	OCF	Finish node, other special chamber, reference: PI02: PUMP TANK	00:00:15		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - S123X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
51	Downstream	S123X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S123



2, 00:00:15, 0.77 m
Finish node, other special chamber, reference: PI02, PUMP TANK

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Abandoned section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
52	1	20/09/26	13:04	J-07955	No Rain Or Snow	Yes	OB3X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	OB3
Road:	Platts Corner	**Inspected Length:**	12.20 m	**Upstream Pipe Depth:**	0.380 m
Location:	Footway	**Total Length:**	12.20 m	**Downstream Node:**	S123
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.797 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY ABANDONED - PIPE NOT FINISHED YET
Recommendations: None

Scale: 1:106



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S123	00:00:00		
0.00	WL	Water level, 0% of the vertical dimension	00:00:04		
5.40	SC	Pipe size changes, new size(s), 150mm high	00:00:41		
6.00	WL	Water level, 10% of the vertical dimension	00:00:51		
7.40	WL	Water level, 0% of the vertical dimension	00:01:02		
10.30	LR	Line deviates right	00:01:17		
12.20	OCF	Finish node, other special chamber, reference: OB3: Channel Drain	00:01:30		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
52	Upstream	OB3X	J-07955	-



1, 00:00:04, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:41, 5.40 m
Pipe size changes, new size(s), 150mm high



3, 00:00:51, 6.00 m
Water level, 10% of the vertical dimension



4, 00:01:02, 7.40 m
Water level, 0% of the vertical dimension



5, 00:01:17, 10.30 m
Line deviates right



6, 00:01:30, 12.20 m
Finish node, other special chamber, reference: OB3, Channel Drain

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
53	1	20/09/26	13:23	J-07955	No Rain Or Snow	Yes	PI02X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	PI02
Road:	Platts Corner	**Inspected Length:**	0.87 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	0.87 m	**Downstream Node:**	S124
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	375 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S124	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.87	OCF	Finish node, other special chamber, reference: PI02: PUMP TANK	00:00:26		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - PI02X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
53	Upstream	PI02X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S124



2, 00:00:26, 0.87 m
Finish node, other special chamber, reference: PI02, PUMP TANK

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
54	1	20/09/26	13:27	J-07955	No Rain Or Snow	Yes	OB2Y


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	OB2
Road:	Platts Corner	**Inspected Length:**	14.83 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	14.83 m	**Downstream Node:**	OB4
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:129



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: OB2	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
14.83	GYF	Finish node, gully, reference: OB4	00:01:21		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB2Y

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
54	Downstream	OB2Y	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: OB2



2, 00:01:21, 14.83 m
Finish node, gully, reference: OB4

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
55	1	20/09/26	13:30	J-07955	No Rain Or Snow	Yes	OB1Y

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	OB1
Road:	Platts Corner	**Inspected Length:**	14.61 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	14.61 m	**Downstream Node:**	OB2
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:127



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: OB2	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
14.61	GYF	Finish node, gully, reference: OB1	00:00:53		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - OB1Y

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
55	Upstream	OB1Y	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: OB2



2, 00:00:53, 14.61 m
Finish node, gully, reference: OB1

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
56	1	20/09/26	13:34	J-07955	No Rain Or Snow	Yes	ABDX

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	ABD
Road:	Platts Corner	**Inspected Length:**	16.36 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	16.36 m	**Downstream Node:**	OB1
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.200 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:142



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: OB1	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
16.36	GYF	Finish node, gully, reference: ABD	00:00:42		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 9/20/2026 - ABDX

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
56	Upstream	ABDX	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: OB1



2, 00:00:42, 16.36 m
Finish node, gully, reference: ABD

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
57	1	07/10/26	8:23	J-07955	No Rain Or Snow	Yes	S116X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S116
Road:	Platts Corner	**Inspected Length:**	20.49 m	**Upstream Pipe Depth:**	1.183 m
Location:	Footway	**Total Length:**	20.49 m	**Downstream Node:**	S117
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.496 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:178



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S117	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension: #	00:00:01		
18.99	LL	Line deviates left	00:00:40		
20.49	ICF	Finish node, inspection chamber, reference: S116	00:00:48		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S116X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
57	Upstream	S116X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S117



2, 00:00:48, 20.49 m
Finish node, inspection chamber, reference: S116

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
58	1	07/10/26	9:23	J-07955	No Rain Or Snow	Yes	S115X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S115
Road:	Platts Corner	**Inspected Length:**	33.81 m	**Upstream Pipe Depth:**	0.800 m
Location:	Footway	**Total Length:**	33.81 m	**Downstream Node:**	S116
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.183 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:293




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S115	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
12.20	JN	Junction at 9 o'clock, 150mm dia	00:00:24		
33.81	ICF	Finish node, inspection chamber, reference: S116	00:01:25		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S115X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
58	Downstream	S115X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S115



2, 00:01:25, 33.81 m
Finish node, inspection chamber, reference: S116

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
59	1	07/10/26	9:29	J-07955	No Rain Or Snow	Yes	S114X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S114
Road:	Platts Corner	**Inspected Length:**	23.80 m	**Upstream Pipe Depth:**	1.000 m
Location:	Footway	**Total Length:**	23.80 m	**Downstream Node:**	S115
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.800 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	225 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:207



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S114	00:00:00		
0.00	WL	Water level, 0% of the vertical dimension	00:00:02		
17.00	CN	Connection other than junction at 11 o'clock, 150mm dia	00:02:23		
23.80	MHF	Finish node, manhole, reference: S115	00:01:34		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S114X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
59	Downstream	S114X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S114



2, 00:00:02, 0.00 m
Water level, 0% of the vertical dimension



3, 00:02:23, 17.00 m
Connection other than junction at 11 o'clock, 150mm dia



4, 00:01:34, 23.80 m
Finish node, manhole, reference: S115

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
60	1	07/10/26	9:35	J-07955	No Rain Or Snow	Yes	GY05X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	GY05
Road:	Platts Corner	**Inspected Length:**	2.86 m	**Upstream Pipe Depth:**	0.280 m
Location:	Footway	**Total Length:**	2.86 m	**Downstream Node:**	S114
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: GY05	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
2.86	ICF	Finish node, inspection chamber, reference: S114	00:00:21		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - GY05X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
60	Downstream	GY05X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: GY05



2, 00:00:21, 2.86 m
Finish node, inspection chamber, reference: S114

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
61	1	07/10/26	9:37	J-07955	No Rain Or Snow	Yes	RWP04X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	RWP04
Road:	Platts Corner	**Inspected Length:**	1.76 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	1.76 m	**Downstream Node:**	S114
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: S114	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
1.76	OCF	Finish node, other special chamber, reference: RWP04: RAIN WATER PIPE	00:00:24		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - RWP04X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
61	Upstream	RWP04X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: S114



2, 00:00:24, 1.76 m
Finish node, other special chamber, reference: RWP04, RAIN WATER PIPE

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
62	1	07/10/26	10:32	J-07955	No Rain Or Snow	Yes	S124X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	S124
Road:	Platts Corner	**Inspected Length:**	21.19 m	**Upstream Pipe Depth:**	2.167 m
Location:	Road	**Total Length:**	21.19 m	**Downstream Node:**	S125
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.900 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	375 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:184



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S125	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
21.19	MHF	Finish node, manhole, reference: S124	00:01:31		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S124X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
62	Upstream	S124X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S125



2, 00:01:31, 21.19 m
Finish node, manhole, reference: S124

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
63	1	07/10/26	12:21	J-07955	No Rain Or Snow	Yes	S125X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S125
Road:	Platts Corner	**Inspected Length:**	30.57 m	**Upstream Pipe Depth:**	1.900 m
Location:	Road	**Total Length:**	30.57 m	**Downstream Node:**	S137
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	3.234 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	375 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:265



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S125	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
30.57	MHF	Finish node, manhole, reference: S137	00:02:28		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S125X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
63	Downstream	S125X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S125



2, 00:02:28, 30.57 m
Finish node, manhole, reference: S137

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
64	1	07/10/26	12:55	J-07955	No Rain Or Snow	Yes	S137X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S137
Road:	Platts Corner	**Inspected Length:**	16.83 m	**Upstream Pipe Depth:**	3.234 m
Location:	Road	**Total Length:**	16.83 m	**Downstream Node:**	S138
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	3.150 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	450 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:146



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S137	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
16.83	MHF	Finish node, manhole, reference: S138	00:01:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S137X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
64	Downstream	S137X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S137



2, 00:01:23, 16.83 m
Finish node, manhole, reference: S138

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
65	1	07/10/26	12:58	J-07955	No Rain Or Snow	Yes	S138X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S138
Road:	Platts Corner	**Inspected Length:**	4.13 m	**Upstream Pipe Depth:**	3.150 m
Location:	Road	**Total Length:**	4.13 m	**Downstream Node:**	S139
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.998 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	450 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S138	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
4.13	CPF	Finish node, catchpit, reference: S139	00:00:56		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S138X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
65	Downstream	S138X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S138



2, 00:00:56, 4.13 m
Finish node, catchpit, reference: S139

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
66	1	07/10/26	13:01	J-07955	No Rain Or Snow	Yes	S139X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S139
Road:	Platts Corner	**Inspected Length:**	3.52 m	**Upstream Pipe Depth:**	0.998 m
Location:	Road	**Total Length:**	3.52 m	**Downstream Node:**	HEADWALL
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	450 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	CP	Start node, catchpit, reference: S139	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
3.52	OFF	Finish node, outfall, reference: HEADWALL	00:00:35		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S139X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
66	Downstream	S139X	J-07955	-



1, 00:00:00, 0.00 m
Start node, catchpit, reference: S139



2, 00:00:35, 3.52 m
Finish node, outfall, reference: HEADWALL

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
67	1	07/10/26	13:51	J-07955	No Rain Or Snow	Yes	HB1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	HB1
Road:	Platts Corner	**Inspected Length:**	1.32 m	**Upstream Pipe Depth:**	2.350 m
Location:	Road	**Total Length:**	1.32 m	**Downstream Node:**	S136
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	4.234 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S136	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
1.32	CPF	Finish node, catchpit, reference: HB1	00:00:34		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - HB1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
67	Upstream	HB1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S136



2, 00:00:34, 1.32 m
Finish node, catchpit, reference: HB1

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
68	1	07/10/26	14:09	J-07955	No Rain Or Snow	Yes	S136X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S136
Road:	Platts Corner	**Inspected Length:**	2.53 m	**Upstream Pipe Depth:**	4.234 m
Location:	Road	**Total Length:**	2.53 m	**Downstream Node:**	S137
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	3.234 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S136	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.33	LD	Line deviates down	00:00:42		
2.53	MHF	Finish node, manhole, reference: S137	00:01:25		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/7/2026 - S136X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
68	Downstream	S136X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S136



2, 00:01:25, 2.53 m
Finish node, manhole, reference: S137

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
69	1	08/10/26	8:04	J-07955	No Rain Or Snow	Yes	F105X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F105
Road:	Platts Corner	**Inspected Length:**	40.50 m	**Upstream Pipe Depth:**	0.767 m
Location:	Footway	**Total Length:**	40.50 m	**Downstream Node:**	F107
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.509 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:351




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F105	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
8.06	JN	Junction at 3 o'clock, 150mm dia	00:00:49		
31.52	JN	Junction at 3 o'clock, 150mm dia	00:02:31		
39.38	JN	Junction at 12 o'clock, 150mm dia	00:03:06		
40.50	ICF	Finish node, inspection chamber, reference: F107	00:03:41		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F105X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
69	Downstream	F105X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F105



2, 00:03:41, 40.50 m
Finish node, inspection chamber, reference: F107

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
70	1	08/10/26	8:14	J-07955	No Rain Or Snow	Yes	F105.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F105.CN1
Road:	Platts Corner	**Inspected Length:**	7.91 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.91 m	**Downstream Node:**	F105
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.767 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:69



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F105	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
1.21	LL	Line deviates left	00:00:11		
7.91	OCF	Finish node, other special chamber, reference: F105.CN1: OTHER	00:00:41		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F105.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
70	Upstream	F105.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F105



2, 00:00:41, 7.91 m
Finish node, other special chamber, reference: F105.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
71	1	08/10/26	8:17	J-07955	No Rain Or Snow	Yes	F105.CN2X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F105.CN2
Road:	Platts Corner	**Inspected Length:**	10.55 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	10.55 m	**Downstream Node:**	F105
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.767 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:92



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F105	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.77	JN	Junction at 9 o'clock, 150mm dia	00:00:09		
10.55	OCF	Finish node, other special chamber, reference: F105.CN2: OTHER	00:00:48		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F105.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
71	Upstream	F105.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F105



2, 00:00:48, 10.55 m
Finish node, other special chamber, reference: F105.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
72	1	08/10/26	8:22	J-07955	No Rain Or Snow	Yes	FG01X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG01
Road:	Platts Corner	**Inspected Length:**	0.88 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	0.88 m	**Downstream Node:**	JNFG01
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: FG01	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.88	BRF	Finish node, major connection without manhole, reference: JNFG01	00:00:35		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG01X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
72	Downstream	FG01X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG01



2, 00:00:35, 0.88 m
Finish node, major connection without manhole, reference: JNFG01

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
73	1	08/10/26	8:41	J-07955	No Rain Or Snow	Yes	FG02X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG02
Road:	Platts Corner	**Inspected Length:**	1.21 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	1.21 m	**Downstream Node:**	JNFG02
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.20 m **FG02**					
0.00	GY	Start node, gully, reference: FG02	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
1.21	BRF	Finish node, major connection without manhole, reference: JNFG02	00:00:15		
JNFG02 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG02X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
73	Downstream	FG02X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG02



2, 00:00:15, 1.21 m
Finish node, major connection without manhole, reference: JNFG02

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
74	1	08/10/26	8:44	J-07955	No Rain Or Snow	Yes	F106X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F106
Road:	Platts Corner	**Inspected Length:**	0.99 m	**Upstream Pipe Depth:**	1.005 m
Location:	Footway	**Total Length:**	0.99 m	**Downstream Node:**	JNF106
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F106	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.22	LD	Line deviates down	00:00:08		
0.99	BRF	Finish node, major connection without manhole, reference: JNF106	00:00:16		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F106X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
74	Downstream	F106X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F106



2, 00:00:16, 0.99 m
Finish node, major connection without manhole, reference: JNF106

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
75	1	08/10/26	8:46	J-07955	No Rain Or Snow	Yes	F106.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F106.CN1
Road:	Platts Corner	**Inspected Length:**	9.67 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	9.67 m	**Downstream Node:**	F106
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.005 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:84




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F106	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
4.61	JN	Junction at 9 o'clock, 100mm dia	00:00:18		
9.67	OCF	Finish node, other special chamber, reference: F106.CN1: OTHER	00:00:38		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F106.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
75	Upstream	F106.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F106



2, 00:00:38, 9.67 m
Finish node, other special chamber, reference: F106.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
76	1	08/10/26	8:49	J-07955	No Rain Or Snow	Yes	F106.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F106.CN2
Road:	Platts Corner	**Inspected Length:**	7.58 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.58 m	**Downstream Node:**	F106
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.005 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:66



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F106	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
7.58	OCF	Finish node, other special chamber, reference: F106.CN2: OTHER	00:00:27		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F106.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
76	Upstream	F106.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F106



2, 00:00:27, 7.58 m
Finish node, other special chamber, reference: F106.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
77	1	08/10/26	8:59	J-07955	No Rain Or Snow	Yes	F108X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F108
Road:	Platts Corner	**Inspected Length:**	1.21 m	**Upstream Pipe Depth:**	0.997 m
Location:	Footway	**Total Length:**	1.21 m	**Downstream Node:**	JNF108
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.00 m **F108**					
0.00	IC	Start node, inspection chamber, reference: F108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
1.21	BRF	Finish node, major connection without manhole, reference: JNF108	00:00:38		
JNF108 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F108X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
77	Downstream	F108X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F108



2, 00:00:38, 1.21 m
Finish node, major connection without manhole, reference: JNF108

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
78	1	08/10/26	9:02	J-07955	No Rain Or Snow	Yes	F108.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F108.CN1
Road:	Platts Corner	**Inspected Length:**	7.47 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.47 m	**Downstream Node:**	F108
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.997 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:65




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
7.47	OCF	Finish node, other special chamber, reference: F108.CN1: OTHER	00:00:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F108.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
78	Upstream	F108.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F108



2, 00:00:23, 7.47 m
Finish node, other special chamber, reference: F108.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
79	1	08/10/26	9:03	J-07955	No Rain Or Snow	Yes	F108.CN2X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F108.CN2
Road:	Platts Corner	**Inspected Length:**	8.79 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	8.79 m	**Downstream Node:**	F108
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.997 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:77




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
8.79	OCF	Finish node, other special chamber, reference: F108.CN2: OTHER	00:00:28		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F108.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
79	Upstream	F108.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F108



2, 00:00:28, 8.79 m
Finish node, other special chamber, reference: F108.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
80	1	08/10/26	9:05	J-07955	No Rain Or Snow	Yes	F108.CN3X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F108.CN3
Road:	Platts Corner	**Inspected Length:**	6.26 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	6.26 m	**Downstream Node:**	F108
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.997 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:55




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F108	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
6.26	REM	General remark: PIPE FROM SHOWER OR SINK	00:01:03		
6.26	OCF	Finish node, other special chamber, reference: F108.CN3: OTHER	00:01:03		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F108.CN3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
80	Upstream	F108.CN3X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F108



2, 00:01:03, 6.26 m
Finish node, other special chamber, reference: F108.CN3, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
81	1	08/10/26	9:09	J-07955	No Rain Or Snow	Yes	FG03X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG03
Road:	Platts Corner	**Inspected Length:**	1.32 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	1.32 m	**Downstream Node:**	JNFG03
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.20 m **FG03**					
0.00	GY	Start node, gully, reference: FG03	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
1.32	BRF	Finish node, major connection without manhole, reference: JNFG03	00:00:26		
JNFG03 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG03X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
81	Downstream	FG03X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG03



2, 00:00:26, 1.32 m
Finish node, major connection without manhole, reference: JNFG03

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
82	1	08/10/26	9:15	J-07955	No Rain Or Snow	Yes	F109X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F109
Road:	Platts Corner	**Inspected Length:**	3.80 m	**Upstream Pipe Depth:**	1.008 m
Location:	Footway	**Total Length:**	3.80 m	**Downstream Node:**	JNF109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	Cured in place lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Epoxy

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.01 m **F109**					
0.00	IC	Start node, inspection chamber, reference: F109	00:00:00		
0.00	WL	Water level, 0% of the vertical dimension	00:00:09		
0.20	LR	Line deviates right	00:00:09		
1.70	LD	Line deviates down	00:00:21		
3.20	LCCIP	Cured-in-place lining, material changes at this point, new material: epoxy	00:00:29		
3.80	LCCIP	Cured-in-place lining ends at this point	00:00:36		
3.80	BRF	Finish node, major connection without manhole, reference: JNF109	00:00:42		
JNF109 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F109X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
82	Downstream	F109X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F109



2, 00:00:09, 0.20 m
Line deviates right



3, 00:00:21, 1.70 m
Line deviates down



4, 00:00:29, 3.20 m
Cured-in-place lining, material changes at this point, new material: epoxy



5, 00:00:36, 3.80 m
Cured-in-place lining ends at this point



6, 00:00:42, 3.80 m
Finish node, major connection without manhole, reference: JNF109

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
83	1	08/10/26	9:16	J-07955	No Rain Or Snow	Yes	F109.CN1X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F109.CN1
Road:	Platts Corner	**Inspected Length:**	6.81 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	6.81 m	**Downstream Node:**	F109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.008 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:59




Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.01 m **F109**					
0.00	IC	Start node, inspection chamber, reference: F109	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
6.81	OCF	Finish node, other special chamber, reference: F109.CN1: OTHER	00:00:27		
F109.CN1 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F109.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
83	Upstream	F109.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F109



2, 00:00:27, 6.81 m
Finish node, other special chamber, reference: F109.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
84	1	08/10/26	9:18	J-07955	No Rain Or Snow	Yes	F109.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F109.CN2
Road:	Platts Corner	**Inspected Length:**	7.91 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.91 m	**Downstream Node:**	F109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.008 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY
Recommendations: None

Scale: 1:69




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F109	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
7.91	OCF	Finish node, other special chamber, reference: F109.CN2: OTHER	00:00:26		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F109.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
84	Upstream	F109.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F109



2, 00:00:26, 7.91 m
Finish node, other special chamber, reference: F109.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
85	1	08/10/26	9:25	J-07955	No Rain Or Snow	Yes	F109.CN3X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F109.CN3
Road:	Platts Corner	**Inspected Length:**	9.23 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	9.23 m	**Downstream Node:**	F109
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.008 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:80



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F109	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
9.23	OCF	Finish node, other special chamber, reference: F109.CN3: OTHER	00:00:27		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F109.CN3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
85	Upstream	F109.CN3X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F109



2, 00:00:27, 9.23 m
Finish node, other special chamber, reference: F109.CN3, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
86	1	08/10/26	9:23	J-07955	No Rain Or Snow	Yes	FG04X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG04
Road:	Platts Corner	**Inspected Length:**	2.64 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	2.64 m	**Downstream Node:**	JNFG04
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 0.20 m **FG04**					
0.00	GY	Start node, gully, reference: FG04	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
2.64	BRF	Finish node, major connection without manhole, reference: JNFG04	00:00:25		
JNFG04 **Depth: 0.00 m**					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG04X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
86	Downstream	FG04X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG04



2, 00:00:25, 2.64 m
Finish node, major connection without manhole, reference: JNFG04

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
87	1	08/10/26	9:34	J-07955	No Rain Or Snow	Yes	F110X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F110
Road:	Platts Corner	**Inspected Length:**	2.08 m	**Upstream Pipe Depth:**	1.057 m
Location:	Footway	**Total Length:**	2.08 m	**Downstream Node:**	JNF110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F110	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
2.08	BRF	Finish node, major connection without manhole, reference: JNF110	00:00:27		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F110X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
87	Downstream	F110X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F110



2, 00:00:27, 2.08 m
Finish node, major connection without manhole, reference: JNF110

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
88	1	08/10/26	9:36	J-07955	No Rain Or Snow	Yes	F110.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F110.CN1
Road:	Platts Corner	**Inspected Length:**	5.82 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	5.82 m	**Downstream Node:**	F110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.057 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:51



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F110	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
5.82	OCF	Finish node, other special chamber, reference: F110.CN1: OTHER	00:01:01		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F110.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
88	Upstream	F110.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F110



2, 00:01:01, 5.82 m
Finish node, other special chamber, reference: F110.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
89	1	08/10/26	9:38	J-07955	No Rain Or Snow	Yes	F110.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F110.CN2
Road:	Platts Corner	**Inspected Length:**	7.47 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.47 m	**Downstream Node:**	F110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.057 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:65



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F110	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
7.47	OCF	Finish node, other special chamber, reference: F110.CN2: OTHER	00:00:51		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F110.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
89	Upstream	F110.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F110



2, 00:00:51, 7.47 m
Finish node, other special chamber, reference: F110.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
90	1	08/10/26	9:40	J-07955	No Rain Or Snow	Yes	F110.CN3X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F110.CN3
Road:	Platts Corner	**Inspected Length:**	8.46 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	8.46 m	**Downstream Node:**	F110
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.057 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:74



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F110.CN3	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
8.46	OCF	Finish node, other special chamber, reference: F110: OTHER	00:00:31		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F110.CN3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
90	Downstream	F110.CN3X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F110.CN3



2, 00:00:31, 8.46 m
Finish node, other special chamber, reference: F110, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
91	1	08/10/26	10:16	J-07955	No Rain Or Snow	Yes	F107X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Crawler	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F107
Road:	Platts Corner	**Inspected Length:**	80.50 m	**Upstream Pipe Depth:**	1.509 m
Location:	Footway	**Total Length:**	80.50 m	**Downstream Node:**	F111
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.625 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:697




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F107	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
7.57	JN	Junction at 3 o'clock, 150mm dia	00:02:41		
7.60	JN	Junction at 3 o'clock, 150mm dia	00:02:44		
23.51	JN	Junction at 2 o'clock, 150mm dia	00:04:10		
41.76	JN	Junction at 12 o'clock, 150mm dia	00:05:34		
54.23	JN	Junction at 12 o'clock, 150mm dia	00:06:30		
69.47	JN	Junction at 12 o'clock, 150mm dia	00:07:43		
80.50	ICF	Finish node, inspection chamber, reference: F111	00:08:42		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F107X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
91	Downstream	F107X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F107



2, 00:08:42, 80.50 m
Finish node, inspection chamber, reference: F111

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
92	1	08/10/26	11:34	J-07955	No Rain Or Snow	Yes	F101.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F101.CN1
Road:	Platts Corner	**Inspected Length:**	5.71 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	5.71 m	**Downstream Node:**	F101
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.800 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F101	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
5.71	OCF	Finish node, other special chamber, reference: F101.CN1: OTHER	00:00:22		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F101.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
92	Upstream	F101.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F101



2, 00:00:22, 5.71 m
Finish node, other special chamber, reference: F101.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
93	1	08/10/26	11:35	J-07955	No Rain Or Snow	Yes	F101.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F101.CN2
Road:	Platts Corner	**Inspected Length:**	7.25 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	7.25 m	**Downstream Node:**	F101
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.800 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:63



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F101	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
7.25	OCF	Finish node, other special chamber, reference: F101.CN2: OTHER	00:00:23		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F101.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
93	Upstream	F101.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F101



2, 00:00:23, 7.25 m
Finish node, other special chamber, reference: F101.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
94	1	08/10/26	11:36	J-07955	No Rain Or Snow	Yes	F101.CN3X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F101.CN3
Road:	Platts Corner	**Inspected Length:**	8.68 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	8.68 m	**Downstream Node:**	F101
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.800 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:76



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F101	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
8.68	OCF	Finish node, other special chamber, reference: F101.CN3: OTHER	00:00:21		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F101.CN3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
94	Upstream	F101.CN3X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F101



2, 00:00:21, 8.68 m
Finish node, other special chamber, reference: F101.CN3, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
95	1	08/10/26	11:39	J-07955	No Rain Or Snow	Yes	FG05X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG05
Road:	Platts Corner	**Inspected Length:**	0.88 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	0.88 m	**Downstream Node:**	JNGH05
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: FG05	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.88	BRF	Finish node, major connection without manhole, reference: JNGH05	00:00:19		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG05X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
95	Downstream	FG05X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG05

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
96	1	08/10/26	11:45	J-07955	No Rain Or Snow	Yes	F101X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F101
Road:	Platts Corner	**Inspected Length:**	21.46 m	**Upstream Pipe Depth:**	0.800 m
Location:	Footway	**Total Length:**	21.46 m	**Downstream Node:**	F102
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.189 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:186




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F101	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
12.52	JN	Junction at 9 o'clock, 150mm dia	00:00:28		
21.46	ICF	Finish node, inspection chamber, reference: F102	00:00:47		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F101X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
96	Downstream	F101X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F101



2, 00:00:47, 21.46 m
Finish node, inspection chamber, reference: F102

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
97	1	08/10/26	11:50	J-07955	No Rain Or Snow	Yes	F102.CN1X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F102.CN1
Road:	Platts Corner	**Inspected Length:**	11.75 m	**Upstream Pipe Depth:**	
Location:	Footway	**Total Length:**	11.75 m	**Downstream Node:**	F102
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.189 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:102



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F102	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
11.75	REM	General remark: NOT INSTALLED	00:00:41		
11.75	OCF	Finish node, other special chamber, reference: F102.CN1: OTHER	00:00:41		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F102.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
97	Upstream	F102.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F102



2, 00:00:41, 11.75 m
Finish node, other special chamber, reference: F102.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
98	1	08/10/26	11:52	J-07955	No Rain Or Snow	Yes	F102.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F102.CN2
Road:	Platts Corner	**Inspected Length:**	6.92 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	6.92 m	**Downstream Node:**	F102
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.189 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:60




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F102	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
6.92	OCF	Finish node, other special chamber, reference: F102.CN2: OTHER	00:00:19		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F102.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
98	Upstream	F102.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F102



2, 00:00:19, 6.92 m
Finish node, other special chamber, reference: F102.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
99	1	08/10/26	11:54	J-07955	No Rain Or Snow	Yes	F102X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F102
Road:	Platts Corner	**Inspected Length:**	11.54 m	**Upstream Pipe Depth:**	1.189 m
Location:	Footway	**Total Length:**	11.54 m	**Downstream Node:**	F111
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.625 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:100




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F102	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
11.54	ICF	Finish node, inspection chamber, reference: F111	00:00:28		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F102X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
99	Downstream	F102X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F102



2, 00:00:28, 11.54 m
Finish node, inspection chamber, reference: F111

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
100	1	08/10/26	12:57	J-07955	No Rain Or Snow	Yes	FG07X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	FG07
Road:	Platts Corner	**Inspected Length:**	0.66 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	0.66 m	**Downstream Node:**	JNFG07
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	GY	Start node, gully, reference: FG07	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.66	BRF	Finish node, major connection without manhole, reference: JNFG07	00:00:14		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG07X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
100	Downstream	FG07X	J-07955	-



1, 00:00:00, 0.00 m
Start node, gully, reference: FG07



2, 00:00:14, 0.66 m
Finish node, major connection without manhole, reference: JNFG07

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
101	1	08/10/26	13:10	J-07955	No Rain Or Snow	Yes	F103.CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F103.CN1
Road:	Platts Corner	**Inspected Length:**	5.27 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	5.27 m	**Downstream Node:**	F103
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:50




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F103	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:03		
5.27	OCF	Finish node, other special chamber, reference: F103.CN1: OTHER	00:00:16		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F103.CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
101	Upstream	F103.CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F103



2, 00:00:16, 5.27 m
Finish node, other special chamber, reference: F103.CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
102	1	08/10/26	13:11	J-07955	No Rain Or Snow	Yes	F103.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F103.CN2
Road:	Platts Corner	**Inspected Length:**	9.78 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	9.78 m	**Downstream Node:**	F103
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:85



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F103	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:02		
0.22	JN	Junction at 3 o'clock, 150mm dia	00:00:04		
9.78	OCF	Finish node, other special chamber, reference: F103.CN2: OTHER	00:00:34		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F103.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
102	Upstream	F103.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F103



2, 00:00:34, 9.78 m
Finish node, other special chamber, reference: F103.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
103	1	08/10/26	13:13	J-07955	No Rain Or Snow	Yes	FG06X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	FG06
Road:	Platts Corner	**Inspected Length:**	11.86 m	**Upstream Pipe Depth:**	0.200 m
Location:	Footway	**Total Length:**	11.86 m	**Downstream Node:**	F103
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.000 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:103




Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: 1.00 m					
F103					
0.00	IC	Start node, inspection chamber, reference: F103	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
11.86	GYF	Finish node, gully, reference: FG06	00:00:28		
FG06					
Depth: 0.20 m					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - FG06X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
103	Upstream	FG06X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F103



2, 00:00:28, 11.86 m
Finish node, gully, reference: FG06

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
104	1	08/10/26	13:27	J-07955	No Rain Or Snow	Yes	F111X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F111
Road:	Platts Corner	**Inspected Length:**	30.56 m	**Upstream Pipe Depth:**	1.625 m
Location:	Footway	**Total Length:**	30.56 m	**Downstream Node:**	EXFWMH6
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	2.970 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:265



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F111	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
30.56	MHF	Finish node, manhole, reference: ExFWMH6	00:01:46		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F111X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
104	Downstream	F111X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F111



2, 00:01:46, 30.56 m
Finish node, manhole, reference: ExFWMH6

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
105	1	08/10/26	13:01	J-07955	No Rain Or Snow	Yes	F104X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	F104
Road:	Platts Corner	**Inspected Length:**	15.67 m	**Upstream Pipe Depth:**	1.192 m
Location:	Footway	**Total Length:**	15.67 m	**Downstream Node:**	F111
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.625 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:136




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F104	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.00	REM	General remark: INCORRECT U/S ID F104	00:00:00		
15.67	ICF	Finish node, inspection chamber, reference: F111	00:00:33		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F104X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
105	Downstream	F104X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F104



2, 00:00:33, 15.67 m
Finish node, inspection chamber, reference: F111

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
106	1	08/10/26	13:05	J-07955	No Rain Or Snow	Yes	F104,CN1X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F104,CN1
Road:	Platts Corner	**Inspected Length:**	9.76 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	9.76 m	**Downstream Node:**	F104
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.192 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:85




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F104	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.00	REM	General remark: INCORRECT ID F104 AND F104.CN1	00:00:00		
4.17	JN	Junction at 9 o'clock, 150mm dia	00:00:12		
9.76	OCF	Finish node, other special chamber, reference: F104,CN1: OTHER	00:00:27		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F104,CN1X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
106	Upstream	F104,CN1X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F104



2, 00:00:27, 9.76 m
Finish node, other special chamber, reference: F104,CN1, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
107	1	08/10/26	13:07	J-07955	No Rain Or Snow	Yes	F104.CN2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Sewer	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	F104.CN2
Road:	Platts Corner	**Inspected Length:**	8.79 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	8.79 m	**Downstream Node:**	F104
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.192 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	100 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:77



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	IC	Start node, inspection chamber, reference: F104	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
0.00	REM	General remark: INCORRECT ID F104 AND F104.CN2	00:00:00		
8.79	OCF	Finish node, other special chamber, reference: F104.CN2: OTHER	00:00:22		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/8/2026 - F104.CN2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
107	Upstream	F104.CN2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, inspection chamber, reference: F104



2, 00:00:22, 8.79 m
Finish node, other special chamber, reference: F104.CN2, OTHER

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
108	1	30/10/26	9:50	J-07955	No Rain Or Snow	Yes	HW2X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	HW2
Road:	Platts Corner	**Inspected Length:**	6.70 m	**Upstream Pipe Depth:**	0.000 m
Location:	Footway	**Total Length:**	6.70 m	**Downstream Node:**	HB2
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	2.100 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	450 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:59



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	CP	Start node, catchpit, reference: HB2	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
6.70	OFF	Finish node, outfall, reference: HW2	00:00:30		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - HW2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
108	Upstream	HW2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, catchpit, reference: HB2



2, 00:00:30, 6.70 m
Finish node, outfall, reference: HW2

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
109	1	30/10/26	8:43	J-07955	No Rain Or Snow	Yes	HB2X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Upstream	**Upstream Node:**	HB2
Road:	Platts Corner	**Inspected Length:**	16.64 m	**Upstream Pipe Depth:**	2.100 m
Location:	Fields, farmland etc	**Total Length:**	16.64 m	**Downstream Node:**	S140
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.750 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:145



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S140	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
16.64	CPF	Finish node, catchpit, reference: HB2	00:01:38		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - HB2X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
109	Upstream	HB2X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S140



2, 00:01:38, 16.64 m
Finish node, catchpit, reference: HB2

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
110	1	30/10/26	8:54	J-07955	No Rain Or Snow	Yes	S140X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S140
Road:	Platts Corner	**Inspected Length:**	57.77 m	**Upstream Pipe Depth:**	0.750 m
Location:	Fields, farmland etc	**Total Length:**	57.77 m	**Downstream Node:**	S141
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.438 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:501



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S140	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
57.77	MHF	Finish node, manhole, reference: S141	00:03:41		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - S140X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
110	Downstream	S140X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S140



2, 00:03:41, 57.77 m
Finish node, manhole, reference: S141

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
111	1	30/10/26	9:41	J-07955	No Rain Or Snow	Yes	S141X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S141
Road:	Platts Corner	**Inspected Length:**	28.46 m	**Upstream Pipe Depth:**	1.438 m
Location:	Fields, farmland etc	**Total Length:**	28.46 m	**Downstream Node:**	S142
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.858 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:247




Position [m]		Code	Observation	MPEG	Photo	Grade
0.00		MH	Start node, manhole, reference: S141	00:00:00		
0.00		WL	Water level, 10% of the vertical dimension	00:00:00		
0.00	S01	RPL	Point repair, localised lining from 12 o'clock to 12 o'clock, start	00:00:00		
27.08		LR	Line deviates right	00:01:30		
27.08	F01	RPL	Point repair, localised lining from 12 o'clock to 12 o'clock, finish	00:01:30		
27.54		LL	Line deviates left	00:01:34		
28.46		MHF	Finish node, manhole, reference: S142	00:01:57		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - S141X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
111	Downstream	S141X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S141



2, 00:00:00, 0.00 m
Point repair, localised lining from 12 o'clock to 12 o'clock, start



3, 00:01:57, 28.46 m
Finish node, manhole, reference: S142

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
112	1	30/10/26	10:01	J-07955	No Rain Or Snow	Yes	S142X


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S142
Road:	Platts Corner	**Inspected Length:**	19.54 m	**Upstream Pipe Depth:**	1.858 m
Location:	Verge	**Total Length:**	19.54 m	**Downstream Node:**	S143
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	0.464 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:170



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S142	00:00:00		
0.00	WL	Water level, 10% of the vertical dimension	00:00:00		
0.77	LR	Line deviates right	00:00:07		
19.54	MHF	Finish node, manhole, reference: S143	00:00:59		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - S142X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
112	Downstream	S142X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S142



2, 00:00:59, 19.54 m
Finish node, manhole, reference: S143

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Completed section inspection

WEB PROJECT CLICK TO OPEN THIS SECTION

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
113	1	30/10/26	10:07	J-07955	No Rain Or Snow	Yes	S143X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
EK	LJ76 ZGT	Pushrod	0.00 m	Private Drain	Not Specified

Town or Village:	Billingshurst	**Inspection Direction:**	Downstream	**Upstream Node:**	S143
Road:	Platts Corner	**Inspected Length:**	26.70 m	**Upstream Pipe Depth:**	0.464 m
Location:	Verge	**Total Length:**	26.70 m	**Downstream Node:**	EX MH
Surface Type:	Asphalt Footway	**Joint Length:**	1.00 m	**Downstream Pipe Depth:**	1.695 m

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:	Gravity drain/sewer	**Dia/Height:**	150 mm
Flow Control:	No flow control	**Material:**	Polyvinyl chloride
Year Constructed:	2026	**Lining Type:**	No Lining
Inspection Purpose:	Post completion condition survey	**Lining Material:**	Vitrified clay

Comments: SURVEY COMPLETE
Recommendations: None

Scale: 1:232




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: S143	00:00:00		
0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
0.92	LR	Line deviates right	00:00:10		
26.58	LR	Line deviates right	00:02:58		
26.70	CPF	Finish node, catchpit, reference: EX MH	00:03:55		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Section Pictures - 10/30/2026 - S143X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
113	Downstream	S143X	J-07955	-



1, 00:00:00, 0.00 m
Start node, manhole, reference: S143



2, 00:03:55, 26.70 m
Finish node, catchpit, reference: EX MH

Aquatech Drain Services Ltd
Holmbush Lane, Woodmancote
Tel. 01273 933705
contact@aquatechdrains.co.uk

Disclaimer

Although every effort has been made to produce a thorough and precise report, Aquatech Drain Services Ltd cannot be held liable for any
discrepancies or omissions. Furthermore Aquatech Drain Services Ltd cannot be held responsible for any actions taken based on the information supplied within this report.