

Heather close silver maples TPO/0919



Tree location and TPO details



Locations of individual trees



Cavity in tree 5585

Inspectors notes

Asymmetry to the west. Large semi-occluded wound on the north-east side of the stem at 1.5m. Unknown fungal fruiting body within, possibly saprophytic. At its deepest point, the prope was able to penetrate to approximately 40cm. When sounded with a mallet a further indication of a cavity beyond was noted.

22-09-20. Since the last inspection and in response to the observations made the tree has received a canopy reduction. While the previously mentioned fungal fruiting body wasn't present, further investigations of the cavity identified additional decay/hollowing. While the tree is producing vast ribs of tissue on the margins of the wound/cavity entrance, the dimensions of the void beyond is anticipated to be reaching an unacceptable level. Weighted towards the adjacent residential property and footpath.

13.9.24 previous reduction points beginning to fail and in some places die off. 40cm probe is disappearing in every direction when probing historic wound on north east side at 1.5m