WTS-1328 Photographs





T11/98 (as numbered on map) – Common Ash showing signs of Ash Die Back



T11/98 Common Ash showing wound in main trunk