
Dingemans Court, Shooting Field, Steyning, West Sussex BN44 3RU



T1 is a birch in severe decline in a closed courtyard in a sheltered residence for elderly people, for which a proposal to fell to ground level has been submitted.

The large amounts major dead wood present in the crown, and the lack of vitality in the remaining crown, taken alongside the decay in, and fungal fruiting bodies on, the base and stem of the tree, making dead wood removal and reduction operations a non-viable solution, the only prudent course of action is removal.