LEVEL MONITORING

for SMS (AXA)

Birchwood, The Street, Slinforld, Horsham, RH13 0RP

Client:	SMS (AXA)
Client Contact:	Refer to iSubs
Claim Number:	12687256K
Client Reference:	IFS-AXA-SUB-25-0125280
Policy Holder:	Mr Senthil Rajan-Edge
Report Date:	4 September 2026
Our Ref:	M25989

SubsNetUK

SubsNetUK

Level Monitoring Readings


The following table shows the reading levels of the various Level Monitoring Station points.


Date	1	2	6	5	4	3	7	8	9	10
13/01/2026	10.0000	9.9275	9.9181	9.9026	9.9031	9.9991	10.0174	9.9080	9.9815	9.9893
11/03/2026	10.0000	9.9275	9.9230	9.9077	9.9080	9.9983	10.0168	9.9131	9.9891	9.9888
07/05/2026	10.0000	9.9275	9.9241	9.9090	9.9101	9.9985	10.0169	9.9149	9.9925	9.9891
30/06/2026	10.0000	9.9276	9.9188	9.9042	9.9066	9.9985	10.0166	9.9139	9.9896	9.9889
27/08/2026	10.0000	9.9277	9.8815	9.8747	9.8820	9.9992	10.0167	9.8818	9.9563	9.9951

Date	11	12	13
13/01/2026	10.6445	10.0936	10.0854
11/03/2026	10.6445	10.0949	10.0851
07/05/2026	10.6433	10.0943	10.0850
30/06/2026	10.6444	10.0944	10.0851
27/08/2026		10.0872	10.0863

Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.








Difference in Reading (mm)
40.0
35.0
30.0
25.0
20.0
15.0
10.0
5.0
0.0
-5.0
-10.0
-15.0
-20.0
-25.0
-30.0
-35.0
-40.0
01/26
03/26
05/26
06/26
08/26
Site Visit Date
11
12
13

SubsNetUK

Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.





FRONT

SubsNetUK

Site Visit Notes

Datum located at P1 on the LH elevation mid point.