Application to perform works on Ash 0932 Wickhurst lane Broadbridge heath TPO/1343



Location of tree



Inspectors' findings



Remove branch at stem, resultant wound will be under 50mm

Smaller secondary branches to be removed to create 5.5m clearance. Wounds far below 25mm in diameter.