

G2: The two stems of these acers have twisted around each other and will only become more of a risk the longer they are left. Trees are also damaging the fence.

T3: Removal of deadwood.

T4: Removal of a twin stem self seeded Holly along the fence line.

T5: Removal of deadwood.

All work is on a health and safety basis and to improve the aesthetics of the trees. None of the work will be detrimental to the trees in anyway, nor will it affect their amenity value.