Tree Code: Sgl/000349

Position: Supressed cherry

Species: Prunus spp. (Cherryp sp.)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// vocab.records.strumming

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



30/04/2025 11:15:

Inspection: 03/11/2026

Features: Growing In - Mown Grass
Target - Parked vehicle(s)
Target - Footpath
Landscape – Parkland

Conditions: Branches - Significant deadwood
Crown - Decline
Crown - Low canopy
Branches - Major bark wound

Visited By: Richard Tilling

Condition: Fair

Tree Size: 2a 5-10h 15-30d

Recommendations: Crown reduction 30% - HDC 18b
Crown lifting - HDC 26 - to 2.5m

Recom Due Date: 03/11/2028

Tree Code: Sgl/000747

Position: 753

Species: Ginkgo biloba (Maidenhair Tree)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// roosters.deferring.capacity

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



16/10/2023 14:48:

Inspection: 03/11/2026

Features:

Conditions: Crown - Low canopy

Visited By: Richard Tilling

Condition: Good

Tree Size: 3b 10-15h 30+d

Recommendations: Crown reduction 20% - HDC 18a - incorrectrequires crown lift over parking bays but it wouldn't come up

Recom Due Date: 04/05/2027

Tree Code: Sgl/000791

Position: 0519 Lime

Species: Tilia spp. (Limep sp.)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// behaving.entitles.coasting

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



22/04/2021 13:31:

Inspection: 03/11/2026

Features:

Conditions: Stem - Basal or trunk epicormic growth

Visited By: Richard Tilling

Condition: Good

Tree Size: 3b 10-15h 30+d

Recommendations: Basal/epicormic growth and suckers removal - HDC 25 - to 6m

Recom Due Date: 02/11/2027

Tree Code: Sgl/000858

Position: 705

Species: Salix spp. (Willow sp.)

Site: St Cuthmans Field, Steyning


Location: Steyning and South-East

what3words: /// broke.impulses.certainly

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



21/11/2022 13:35:

Inspection: 03/11/2026

Features:

Conditions: Crown - Pollard regrown

Visited By: Richard Tilling

Condition: Fair

Tree Size: 3c 15-20 61-100

Recommendations: Pollard, re-pollard - HDC 8a

Recom Due Date: 04/05/2027

Tree Code: Sgl/002393

Position: 703

Species: Salix spp. (Willow sp.)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// atlas.numeral.cages

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



04/08/2025 15:50:

Inspection: 03/11/2026

Features:

Conditions: Crown - Pollard regrown

Visited By: Richard Tilling

Condition: Fair

Tree Size: 3c 15-20 61-100

Recommendations: Pollard, re-pollard - HDC 8a

Recom Due Date: 04/05/2027

Tree Code: Sgl/003631

Position: 0046 Silver maple

Species: Acer saccharinum (Silver Maple)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// fillers.organist.spoils

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



01/06/2023 11:43:

Inspection: 03/11/2026

Features:

Conditions:

Visited By: Richard Tilling

Condition: Poor

Tree Size: 3c 15-20 61-100

Recommendations: Pollard, maiden pollard - HDC 7a - to 7m

Recom Due Date: 04/05/2027

Tree Code: Sgl/003705

Position: 0018 field maple

Species: Acer campestre (Field Maple)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// fluffed.hails.etchings

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



28/02/2019 10:56:

Inspection: 03/11/2026

Features:

Conditions:

Visited By: Richard Tilling

Condition: Good

Tree Size: 3b 10-15h 30+d

Recommendations: Ivy/climbing plant removal - HDC 30
Crown lifting - HDC 26 - over parking bays to 5m

Recom Due Date: 04/05/2027

Tree Code: Sgl/004319

Position: 0053 Possibly ATI 285017 Notable

Species: Salix alba (White Willow)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// raven.prancing.salads

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



28/02/2019 15:38:

Inspection: 03/11/2026

Features:

Conditions:

Visited By: Richard Tilling

Condition: Fair

Tree Size: 3c 15-20 61-100

Recommendations: Pollard, re-pollard - HDC 8a

Recom Due Date: 04/05/2027

Tree Code: Sgl/005322

Position: 768

Species: Fraxinus excelsior (Common Ash)

Site: St Cuthmans Field, Steyning


Location: Steyning and South-East

what3words: /// rucksack.indoors.mixers

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



30/10/2026 11:55: Fallen branch Oct 26

Inspection: 03/11/2026

Features:

Conditions:

Visited By: Richard Tilling

Condition: Good

Tree Size: 3c 15-20h 30-60

Recommendations: Crown reduction 40% - HDC 18c

Recom Due Date: 04/05/2027

Tree Code: Sgl/005599

Position: 102 Corkscrew willow

Species: Salix matsudana 'Tortuosa' (Corkscrew Willow)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// aura.downhill.negotiators

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



01/06/2023 11:36:

Inspection: 03/11/2026

Features: Target – Play Area

Conditions: Branches - Cavities
Crown - Poor form
Crown - Asymmetric Crown

Visited By: Richard Tilling

Condition: Fair

Tree Size: 3b 10-15h 30+d

Recommendations: Crown reduction 40% - HDC 18c - remove 2m from primary scaffold limbs

Recom Due Date: 04/05/2027

Tree Code: Sgl/006466

Position: 0067 Alder

Species: Alnus glutinosa (Common Alder)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// bulge.curtail.land

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



15/08/2022 08:39:

Inspection: 03/11/2026

Features: Adjacent - Building - within 3m
Adjacent - Other
Growing In - Mown Grass
Target - Wall/Fence
Target - Footpath
Target - Building

Conditions: Crown - Pollard historic

Visited By: Richard Tilling

Condition: Good

Tree Size: 3d 15-20 30-60

Recommendations: Pollard, re-pollard - HDC 8a

Recom Due Date: 03/11/2028

Tree Code: Sgl/006549

Position: 704

Species: Salix spp. (Willow sp.)

Site: St Cuthmans Field, Steyning

Location: Steyning and South-East

what3words: /// acrobatic.symphony.nipping

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



01/06/2023 11:07:

Inspection: 03/11/2026

Features:

Conditions: Crown - Pollard regrown

Visited By: Richard Tilling

Condition: Fair

Tree Size: 3c 15-20 61-100

Recommendations: Pollard, re-pollard - HDC 8a

Recom Due Date: 04/05/2027

Tree Code: Sgl/012954

Position:

Species: Robinia pseudoacacia (False Acacia)

Site: St Cuthmans Field, Steyning

Location: Horsham- Forest

what3words: /// indicated.tastes.porridge

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No

Inspection: 03/11/2026

Features: Target - Parked vehicle(s)
Target - Footpath
Landscape – Parkland

Conditions: Stem - Ivy or climbing plant

Visited By: Richard Tilling

Condition: Good

Tree Size: 2c 15-20h 15-30

Recommendations: Ivy/climbing plant removal - HDC 30

Recom Due Date: 04/05/2027

Tree Code: Sgl/012963

Position: 742

Species: Tilia x europaea (Common Lime)

Site: St Cuthmans Field, Steyning

Location: Horsham- Forest

what3words: /// defining.quibble.perplexed

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No



03/11/2026 13:46: lime

Inspection: 03/11/2026

Features:

Conditions: Crown - Pollard regrown

Visited By: Richard Tilling

Condition: Poor

Tree Size: 3b 10-15h 30+d

Recommendations: Pollard, re-pollard - HDC 8a - remove 50% of existing height due to recent limb failure

Recom Due Date: 04/05/2027



03/11/2026 13:46: lime

Tree Code: Sgl/012971

Position: 757

Species: Acer campestre (Field Maple)

Site: St Cuthmans Field, Steyning

Location: Horsham- Forest

what3words: /// lorry.occupiers.examiner

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No

Inspection: 03/11/2026

Features:

Conditions:

Visited By: Richard Tilling

Condition: Excellent

Tree Size: 3a 0-10h 30+d

Recommendations: Deadwood, removal of major (over 25mm diameter) - HDC 28

Recom Due Date: 04/05/2027

Tree Code: Sgl/012973

Position:

Species: Crataegus monogyna (Hawthorn)

Site: St Cuthmans Field, Steyning

Location: Horsham- Forest

what3words: /// imply.exile.budding

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No

Inspection: 03/11/2026

Features:

Conditions: Crown - Decline - 80% dead

Visited By: Richard Tilling

Condition: Dying

Tree Size: 1b 5-10h 0-15d

Recommendations: Fell, clear/unrestricted - HDC 1 - leave at 2m height stump

Recom Due Date: 04/05/2027

Tree Code: Sgl/012975

Position:

Species: Carpinus betulus (Hornbeam)

Site: St Cuthmans Field, Steyning

Location: Horsham- Forest

what3words: /// manly.scanty.strongly

Felled: No **TPO:** No

Brace: No **Ash DB:** No

ConArea: Yes **Utilities:** No

Inspection: 03/11/2026

Features:

Conditions: Crown - Low canopy

Visited By: Richard Tilling

Condition: Good

Tree Size: 3c 15-20 61-100

Recommendations: Crown lifting - HDC 26 - lowest limb over parking bays

Recom Due Date: 03/11/2028