



Key	
	Existing trees to be retained
	Existing trees to be removed
	New indicative tree planting (by others)
V	Visitor parking space
UP	Un-allocated parking space
G	Garage
CP	Car port
RS	Refuse store
CS	Cycle store
RCP	Refuse collection point
SCS	Sheffield cycle stand
T	Timber bollard
LB	Lockable bollard for emergency access

Note: Refer to drawing no. 1644 / P / 10.05 for details of Boundary Treatments.

Note: Refer to drawing no. 1644 / P / 10.05 for details of Boundary Treatments.

in pump station and parking relocated.

Issue type H14 introduced. Areas of open space increased, scheme amended to suit 155, 216, 216, 283, 284 & 285 replaced with H2. Footpaths amended.

Issue ponds amended.

Replaced. Apartments 115-130 & 131-145 swapped. Poles 216, 216, 283 & 285 replaced with H1.

Issue links added to Mercer Road. Footpath network increased throughout the site.

Issue amended in accordance with landscape architects comments. Junction with Langthorne Road relocated. Amended to increase offers to stop protection area. Dwellings repositioned accordingly. Poles 37-40 H5 replaced 153, Poles 38 replaced with H16. Poles 112 H2 replaced with H1. The nos. 104 and 124 amended. Signage relocated.

Issue pond and employee comments. Two pump stations added. Junction north increased to facilitate refuse tracking. Roads amended to facilitate 22m forward visibility. Dwellings repositioned accordingly. Poles 105, 109 & 140 replaced with H13. Poles 28 & 320 H1 replaced with H15. Substations added.