

NOTES
 SURVEY IS BASED ON OS GRID SYSTEM
 ORIGINATING FROM STATION 3
 @ E 510954.272, N 115149.740, RL 67.037

Every effort has been made to survey the area as indicated. Where detail is inaccessible or obscured from view it has been deemed unable to survey.

LAYER INFORMATION

Bank	EMPTTY
Bottom of bank	Downed bank arrow
Boundaries	Boundary line and markers
Edge of Concrete	Edge of concrete surface
Edge of Road	Edge of road surface
Footpath	Footpath
Fence	Quarrel, fence and boundary lines
Gully	Water course line
Gully	Water drainage
Hedge	Edge of hedge
Manhole	Man hole and flow
Manhole	Man hole and flow
Overhead Cables	Overhead cables and utility poles
Road Markings	Road markings
Roofline	Roofline
Sign Post	Sign post
Spot Levels	Spot levels
Top and Back of Kerb	Top and back of kerb
Tree	Tree
Unexcavated Structure	Unexcavated structure
Wall	Wall


Line types and Symbols

Building Lines	100.40
Rooflines	100.40
Top & Back of Kerb	100.40
Edge of Surface / Footpath	100.40
Edge of Road	100.40
Edge of Concrete	100.40
Top of bank	100.40
Bottom of bank	100.40
Fence / Handrail	100.40
Overhead Cables	100.40

Garden Line	Scrub Line	Road Markings	Hedge Line
Gullies / Waste Water	Man holes & Flow	Walls	Steps
Trees	Spot Levels	Plant	Gates

Control Stations

Point Number	Easting	Northing	Elevation	Description
BS3	510954.272	115149.740	67.037	MLT/NAL
BS4	510954.281	115149.740	68.000	MLT/NAL
BS5	510954.258	115149.465	68.875	MLT/NAL



Rev.	Date	Description

Client: Ailsa & Shaun Tavares

Drawing Title: Topographical Survey Layout

Scale: Not to Scale

Date: 01/03/2023

Drawn: DH

Checked: SE

Job Title: Amberley Cottage, Merrywood Lane, Thakeham, RH20 3HD

Job No: 017 02 23

Drawing No: Layout

Rev: -