

LEVEL MONITORING

for SMS (AXA)

1 Leith View Cottages, Dorking Road, Kingsfold, Horsham, RH12 3SB

Client:	SMS (AXA)
Client Contact:	Ian Domigan
Claim Number:	12685978D
Client Reference:	IFS-AXA-SUB-25-0123752
Policy Holder:	Mr Ben Diab
Report Date:	5 September 2026
Our Ref:	M25414

Level Monitoring Readings


The following table shows the reading levels of the various Level Monitoring Station points.


Date	1	2	3	4	5	6	7	8	9	10
07/11/2025	10.0000	9.7361	9.6422	9.5566	9.4068	9.3899	10.1501	10.1717	9.5054	9.4950
13/01/2026	10.0000	9.7365	9.6427	9.5571	9.4067	9.3965	10.1534	10.1743	9.5068	9.4965
11/03/2026	10.0000	9.7370	9.6428	9.5570	9.4064	9.3979	10.1569	10.1745	9.5061	9.4966
07/05/2026	10.0000	9.7365	9.6425	9.5568	9.4065	9.4003	10.1580	10.1752	9.5064	9.4986
30/06/2026	10.0000	9.7361	9.6419	9.5560	9.4051	9.3907	10.1517	10.1729	9.5046	9.4951
27/08/2026	10.0000	9.7365	9.6433	9.5586	9.4076	9.3743	10.1384	10.1704	9.5083	9.4963

Date	11
07/11/2025	10.1084
13/01/2026	10.1096
11/03/2026	10.1095
07/05/2026	10.1099
30/06/2026	10.1095
27/08/2026	10.1065

Level Monitoring Difference Graphs



The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.





Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

Datum located at P1 on the front elevation LHS of front door.