

LEVEL MONITORING

for SMS (LBG)

Montrose House, Twittenside, Steyning, BN44 3TW

Client: SMS (LBG)

Client Contact: Refer to iSubs

Claim Number: [REDACTED] 1

Client Reference: [REDACTED]

Policy Holder: [REDACTED]

Report Date: 4 February 2026

Our Ref: [REDACTED]



Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	2	1	12	11	10	9	8	4	3	7
01/10/2025	10.0039	10.0000	9.1720	9.2525	9.2500	9.2527	9.2454	9.4088	9.3999	9.1908
03/12/2025	10.0040	10.0000	9.1723	9.2526	9.2500	9.2532	9.2469	9.4094	9.3999	9.1920
29/01/2026	10.0039	10.0000	9.1731	9.2537	9.2517	9.2552	9.2517	9.4099	9.4004	9.1978
Date	6	5								
01/10/2025	9.2001	9.4127								
03/12/2025	9.2028	9.4157								
29/01/2026	9.2072	9.4191								

Level Monitoring Difference Graphs



The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.





Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

Datum located at P1 on the front elevation as per instruction.