

VALIDATION REPORT

Site

**FORMER SMITH & WESTERN,
NORTH PARADE, HORSHAM,
WEST SUSSEX RH12 2QR**

Client

HYSTAR CONSTRUCTION LTD

Report Ref

25/12375/B/KJC

Issued

DECEMBER 2025


ALBURY S.I. LTD

Geotechnical & Environmental Specialists

Miltons Yard,
Petworth Road,
Witley,
Surrey GU8 5LH

01428 684 836
info@alburysi.co.uk
www.alburysi.co.uk



DOCUMENT CONTROL				
Report Title	Validation Report			
Contract	North Parade, Horsham			
Client	Hystar Construction Ltd			
Report Reference	25/12375/B/KJC			
Prepared by	K J Clark BSc Hons Director			
Approved by	G C D Owens BSc MSc FGS MEnvSc Director			
DOCUMENT HISTORY				
Revision	Status	Date	Issued by	Revision Detail
0	Final	09/12/2025	VW	

Albury S.I. Limited has prepared this Report with reasonable skill and care for the sole use of the Client in accordance with the terms and conditions of the contract under which our services were provided. No duty of care and no contractual obligation (whether expressed or implied) is owed to any third party. Should any third party rely on this Report then they do so at their own risk and Albury S.I. Limited shall have no liability whether in contract or in tort, in negligence, for breach of statutory duty or otherwise to any such party. No warranty, expressed or implied, is made as to the professional advice included in this Report or any services provided by Albury S.I. Limited.

The following foreword should be read in conjunction with this report. Any variations on the general procedures outlined below are indicated in the text.

FOREWORD

The recommendations made and opinions expressed in this Report are based on the strata conditions revealed by the fieldworks as indicated on the exploratory records, together with an assessment of the data from in situ and laboratory tests. No liability can be accepted for conditions which have not been revealed by the fieldworks, for example, between exploratory positions. While this Report may offer opinions on the possible configuration of strata, both between the excavations and below the maximum depth achieved by the investigation, these comments are for guidance only and no liability can be accepted for their accuracy. The data obtained relate to the conditions which are relevant at the time of the investigation.

The groundwater observations entered on exploratory records are those noted at the time of the investigation. The normal rate of progress does not usually permit the recording of any equilibrium water level for any one water strike. It should be noted that groundwater levels are prone to seasonal variation and to changes in local drainage conditions. The word 'none' indicates that groundwater was sealed off by the borehole casing or that no water was observed in the exploratory hole upon completion.

It should be appreciated that this report does not constitute a Geotechnical Design Report (GDR) as defined in Eurocode 7 and no aspect of this report constitutes a design. Specific sections of this report are generally in line with the guidance set out in Eurocode 7 for a Ground Investigation Report (GIR), as defined within BS EN 1997:-2 (2024). This provides guidance on the number and spacing of investigation positions, methods of investigation and sample quality class to be achieved which may not have been met by this investigation.

This Report is prepared for the specific purpose stated and in relation to the development proposals or usage indicated to Albury S.I. Limited at the time of preparation. The recommendations should not be used for adjacent schemes and may not be appropriate for alternative proposals.

This Report is the Copyright of Albury S.I. Limited with whom the master copy resides. Further electronic copies can be obtained subject to the clients permission.

REPORT REF: 25/12375/B/KJC
CONTRACT: NORTH PARADE, HORSHAM

TABLE OF CONTENTS

DOCUMENT CONTROL
FOREWORD

1 INTRODUCTION..... 1
2 VALIDATION..... 2
3 SUMMARY 3

REFERENCES
LIST OF ABBREVIATIONS

FIGURES

1 External Landscaping Plan
2 Photographs – Reduced Level
3 Test Location Plan
4 Photographs - Remediation

APPENDICES

1 Waste Transfer Notes
2 Imported Materials - Topsoil
3 Topsoil Analysis/Screening Criteria

1 INTRODUCTION

It is proposed to redevelop the site for residential use with associated hardstanding and soft landscaping. This Validation Statement provides documentary evidence that no active pollutant linkages are present with regards to land contamination and that the site is suitable for the intended residential use.

Albury S.I. Ltd were commissioned to undertake a Phase 1 Desk Study and Phase 2 Intrusive Investigation by the former site owners Smith & Western to provide information to enable a geo-environmental appraisal of the site to be completed. Subsequently, a Remediation Method Statement was prepared for the site for Hystar Construction Ltd the site developer. The following reports should be considered together with this Validation report:

- ***Phase 1 Desk Study and Phase 2 Site Investigation Report***
Albury S.I. Ltd - 22/12375/KJC issued June 2022
- ***Phase 3 Remediation Method Statement***
Albury S.I. Ltd - 22/12375/A/KJC issued December 2023

Briefly, the Phase 1 and 2 investigation undertaken in June 2022 comprised ten investigatory locations of shallow boreholes and trial pits formed using hand-held window sampling and a sample of the made ground at six locations was tested for a background suite of contaminants including heavy metals, TPH, PAH and an asbestos screen. Based upon the findings, remedial measures were proposed as part of the redevelopment in the proposed soft landscaped and garden areas with the excavation and replacement of the unsuitable made ground with certified clean material and topsoil being undertaken. These measures need not necessarily be undertaken beneath the proposed buildings or permanent hardstanding.

The Remediation Strategy confirmed that the impacted soils should be excavated within all soft landscaped areas to the depth required below soft landscaping formation level and replaced with clean granular soil of 450mm thickness. A minimum thickness of certified topsoil of 150mm thickness, to act as a growing medium, will need to be provided above the granular layer.

This Validation Statement contains documentary evidence supplied by the Client, which confirms that the outlined remedial measures have been implemented and that the site is now suitable for use.

2 VALIDATION

The site plan, drawing no. 25/12375/B/1 in Figure 1 shows the final development layout indicating the areas of soft landscaping.

Photographs have been supplied by the Client and are presented in Figure 2, which confirm that the site as a whole was reduced level in level by 500mm prior to commencement of the development.

The excavated soil was removed from site between 20th and 23rd March 2024, and the documentation supplied by the Client is presented in Appendix 1, which confirms that licenced waste carriers Britannia Crest Recycling removed the spoil from site, including one load of hazardous material. The general spoil and hazardous waste were transferred to the Redhill Landfill Site operated by Biffa.

2.1 Imported Materials

The landscaped areas were infilled with sharp, washed sand supplied by Day Aggregates with six loads being delivered to site by Kenward between 3rd and 11th November 2025, to provide a 450mm thickness of subsoil. Four loads of topsoil supplied by Bury Hill Landscape Supplies Ltd were also delivered to site by Kenward between 3rd and 12th November, 2025. The delivery notes from Kenward for the imported sand and topsoil are presented in Appendix 2 and confirm these dates. Geochemical certification sheets have been provided for the imported topsoil completed by Tim O'Hare Associates and are included in Appendix 2, which confirm the suitability of the topsoil for use in a residential setting.

The client has provided photographs of trial pits confirming that the correct thicknesses of sand and topsoil have been provided. These are included in Figure 4. Geochemical analyses of imported topsoil has also been carried out. A visit to site was made on 24th November, 2025, to obtain samples from five locations within the landscaped areas as indicated on the plan included in Figure 3.

Each sample comprised a representative composite taken from the full depth of the topsoil layer. Given that all soil uniformly comprised topsoil from a single supplier, there were no discreet layers, which would require targeted sampling.

The samples were analysed for a background suite of contaminants, which includes various inorganic compounds (primarily metals), speciated PAH, TPH CWG and an asbestos screen. The results of the analyses are included in Appendix 3.

A generic assessment of the chronic or long-term risk to human health from soil contamination has been made using the available generic screening criteria. The screening values include the Category 4 Screening Levels [C4SLs] (DEFRA, 2014) and Suitable for Use Levels [S4ULs] (LQM/CIEH, 2014) derived using the CLEA software. The screening criteria were agreed with the Local Authority as part of the RMS and are included in Appendix 3 for convenience. It should be appreciated that these do not consider the short-term or acute risks, such as to construction workers or SI personnel.

The results of the testing were compared with the guidance for the proposed land use category, “Residential (with Consumption of Home-Grown Produce)” and a soil organic matter as appropriate for the given sample. The results indicate that no elevated levels of any contaminant were identified within the samples tested. Furthermore, no asbestos was identified in any sample. It is, therefore, considered that the imported materials do not pose any significant risk in terms of contamination exposure and are suitable for their intended use.

3 SUMMARY

It is considered that the information presented in the attached Figures and Appendices to this report confirm that the required remediation has been undertaken. The implementation of a cover system of clean soils in areas of soft landscaping will reduce the exposure risk via the dermal and ingestion exposure pathways between any potential residual contamination and future site receptors/ residential end-users.

REFERENCES

- British Standards (2016). Methods of test for soils for civil engineering purposes, BS 1377-1:2016. *British Standard Institution, London.*
- British Standards (2011). Investigation of potentially contaminated sites. Code of Practice. BS 10175+A2:2017. *British Standard Institution, London.*
- British Standards (2013). Guidance on investigations for ground gas. Permanent gases and Volatile Organic Compounds (VOCs). BS 8576. *British Standard Institution, London.*
- British Standards (2015). Code of practice for the design of protective measures for methane and carbon dioxide ground gases for new buildings. BS 8485+A1:2019. *British Standard Institution, London.*
- British Standards (2015). Code of practice for ground investigations, BS 5930:2015. *British Standard Institution, London.*
- Building Research Establishment [BRE] (2004). *Cover systems for land regeneration: Thickness of cover systems for contaminated land (BR 465).* BRE Watford, UK.
- Building Research Establishment [BRE] (2005). *Concrete in aggressive ground: Special Digest 1* (3rd Ed.). BRE Watford, UK.
- Building Research Establishment [BRE] (2015). *Guidance on protective measures for new buildings. (BR 212).* BRE Watford, UK.
- Contaminated land: Applications in Real Environments. (2013). *SP1010: Development of Category 4 Screening Levels for Assessment of Land Affected by Contamination – Final Project Report.*
- Chartered Institute of Environmental Health and Contaminated Land: Applications in Real Environments (2008). *The Guidance on Comparing Soil Contamination Data with Critical Concentration.* London, UK.
- Environment Agency (2004). *Model Procedures for the Management of Contaminated Land.* Contaminated Land Report (CLR) 11, SC02000028, Environment Agency, Bristol, UK.
- Environment Agency (2015). Interpretation of the definition and classification of hazardous waste. 1st edition. Technical Guidance WM3. *Environment Agency, UK.*
- Nathanail, C.P., McCaffrey, C., Gillett, A.G., Ogden, R.C. and Nathanail, J.F. (2015). *The LQM/CIEH S4ULs for Human Health Risk Assessment.* Land Quality Press, Nottingham. Publication Number S4UL3073.
- Stroud, M. A. (1974). The standard penetration test in insensitive clays and soft rocks. *Proceedings of the European Symposium on Penetration Testing, Stockholm, 2, 367-375.*

LIST OF ABBREVIATIONS

AOD	-	Above Ordnance Datum
ACM	-	Asbestos-containing Material
AST	-	Above-ground Storage Tank
BGS	-	British Geological Survey
BH	-	Borehole
BRE	-	Building Research Establishment
BSI	-	British Standards Institution
BS	-	British Standard
C4SL	-	Category Four Screening Level
CIRIA	-	Construction Industry Research and Information Association
CP	-	Cable Percussive
DPH	-	Dynamic Probing Heavy
DPSH	-	Dynamic Probing Super Heavy
EA	-	Environment Agency
GAC	-	Generic Assessment Criteria
LL	-	Liquid Limit
mAOD	-	Metres Above Ordnance Datum
mBGL	-	Metres Below Ground Level
mOD	-	Metres Ordnance Datum
OS	-	Ordnance Survey
PAH	-	Polycyclic Aromatic Hydrocarbons
PCB	-	Polychlorinated Biphenyl
PID	-	Photo Ionisation Detector
PL	-	Plastic Limit
PSD	-	Particle Size Distribution
SGV	-	Soil Guideline Value
SOM	-	Soil Organic Matter
SPT	-	Standard Penetration Test
SPZ	-	Source Protection Zone
SVOC	-	Semi-volatile Organic Compounds
TPH	-	Total Petroleum Hydrocarbon
UST	-	Underground Storage Tank
UXB	-	Unexploded Bombs
UXO	-	Unexploded Ordnance
VOC	-	Volatile Organic Compound

FIGURE 1

EXTERNAL LANDSCAPING PLAN

-  PLANTING BEDS (PLANTING SCHEDULE BY LANDSCAPE DESIGNER)
-  MATURE / SEMIMATURE TREES (PLANTING SCHEDULE BY LANDSCAPE DESIGNER)
-  FOUNTAIN / WATER FEATURE (BY LANDSCAPE DESIGNER) - REQUIRES POWER
-  ROOF PROTECTION ZONES (WITH NO DIG CONSTRUCTION ZONE HATCHED)

Legend:

-  Soft landscaped areas requiring remediation
-  Soft landscaped areas requiring remediation



Title: Remediation Plan

Dwg No: 23/12375/B/1

Drawn by: KJC

Client: Hystar Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 23/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 13/12/2023



ALBURY S.I. LTD

Miltons Yard, Petworth Road,
Witley, Surrey GU8 5LH
www.alburysi.co.uk

FIGURE 2

PHOTOGRAPHS – REDUCED LEVEL



Title: Reduced Level
Dwg No: 25/12375/B/2
Drawn by: KJC

Client: Hystar Construction Ltd
Contract: North Parade, Horsham
Job Ref: 25/12375/B/KJC
Scale: NTS
Revision: 0
Issue Date: 03/12/2025



Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysl.co.uk

FIGURE 3

TEST LOCATION PLAN

-  PLANTING BEDS (PLANTING SCHEDULE BY LANDSCAPE DESIGNER)
-  MATURE / SEMI-MATURE TREES (PLANTING SCHEDULE BY LANDSCAPE DESIGNER)
-  FOUNTAIN / WATER FEATURE (BY LANDSCAPE DESIGNER) - REQUIRES POWER
-  ROOF PROTECTION ZONES (WITH NO OIG CONSTRUCTION ZONE HATCHED)

Legend:

-  Soft landscaped areas requiring remediation
- 



Title: Remediation Plan

Dwg No: 25/12375/B/3

Drawn by: KJC

Client: Hystar Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 08/12/2025



ALBURY S.I. LTD

Miltons Yard, Petworth Road,
Witley, Surrey GU8 5LH
www.alburysi.co.uk

FIGURE 4

PHOTOGRAPHS - REMEDIATION



Excavation 1

Title: Remediation Photos

Dwg No: 25/12375/B/4

Drawn by: KJC

Client: Hystar
Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 03/12/2025



ALBURY S.I. LTD

Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysl.co.uk



Excavation 2

Title: Remediation Photos

Dwg No: 25/12375/B/5

Drawn by: KJC

Client: Hystar
Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 03/12/2025



ALBURY S.I. LTD

Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysl.co.uk



Excavation 3

Title: Remediation Photos

Dwg No: 25/12375/B/6

Drawn by: KJC

Client: Hystar
Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 03/12/2025



ALBURY S.I. LTD

Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysl.co.uk



Excavation 4

Title: Remediation Photos

Dwg No: 25/12375/B/7

Drawn by: KJC

Client: Hystar
Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 03/12/2025



ALBURY S.I. LTD

Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysi.co.uk



Excavation 5

Title: Remediation Photos

Dwg No: 25/12375/B/8

Drawn by: KJC

Client: Hystar
Construction Ltd

Contract: North Parade,
Horsham

Job Ref: 25/12375/B/KJC

Scale: NTS

Revision: 0

Issue Date: 03/12/2025

 **ALBURY S.I. LTD**

Miltons Yard, Petworth Rd,
Witley, Surrey GU8 5LH
www.alburysl.co.uk

APPENDIX 1

WASTE TRANSFER NOTES



BRITANIACREST RECYCLING

Britaniacrest Recycling Ltd

24-26 Reigate Road

Hookwood

RH6 0HJ

T: 01293 820021

F: 01293 776988

e: accounts@britaniacrest.net

w: www.britaniacrestrecycling.co.uk

INVOICE

HYSTAR CONSTRUCTION LTD
HYSTAR HOUSE
1A SOUTH ROAD
REIGATE
SURREY
RH2 7LB

✓ Invoice No.	
Tax Point Date	23/03/2024
Account No.	

Date	Ticket	Product	Unit	Qty	PPU	Net
20/03/24	7768368	MUCK AWAY	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768369	MUCK AWAY	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768370	MUCK AWAY	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768371	MUCK AWAY	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768372	MUCK AWAY	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768373	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7768375	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770070	TARMAC BREAKOUT	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770081	CONCRETE	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770088	CONCRETE	Load	1.00		
	Order No.: MUST.	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770092	CONCRETE	Load	1.00		



BRITANIACREST RECYCLING

Britaniacrest Recycling Ltd

24-26 Reigate Road

Hookwood

RH6 0HJ

T: 01293 820021

F: 01293 776988

e: accounts@britaniacrest.net

w: www.britaniacrestrecycling.co.uk

INVOICE

HYSTAR CONSTRUCTION LTD
HYSTAR HOUSE
1A SOUTH ROAD
REIGATE
SURREY
RH2 7LB

✓ Invoice No.	
Tax Point Date	23/03/2024
Account No.	

Date	Ticket	Product	Unit	Qty	PPU	Net
21/03/24	7769630	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769631	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769632	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769634	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769635	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769636	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769637	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
21/03/24	7769647	HAZADOUS SOIL 170503 CONTAINING DANGEROUS SUBSTANCES	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770229	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				
20/03/24	7770230	MUCK AWAY	Load	1.00		
	Order No.: MUST	THE OLD SMITH AND WESTERN,37 NORTH PARADE,RH12 2QR				

**DUTY OF CARE
CONTROLLED WASTE
TRANSFER NOTE /
CONVEYANCE NOTE**

Registered in England 2798579

VAT No. 7833 971 87

ON BEHALF OF (Producer / Current Holder)

HYSTAR CONSTRUCTION LTD

Name and Address of Site:HYSTAR CONSTRUCTION LTD
THE OLD SMITH AND WESTERN
37 NORTH PARADE
HORSHAM
RH12 2QR**SIC Code:** 41100**Contact Tel:** [REDACTED]**Ticket No:** [REDACTED]**Collection/Disposal Site:**

Biffa Redhill

Date & Time: 21/03/2024 00:00:00**Vehicle Reg:** GL19FWY**Haulier:** BRITANIACREST RECYCLING**Order No:** [REDACTED]**Cust Order No:** MUST

Product	Gross	Tare	Net	Qty	Unit
HAZADOUS SOIL 170503 CONTAINING DANGEWROUS	0.00	0.00	0.00	1.00	LOAD

Time On Site : 21/03/2024 06:54:21

Time Off Site : 21/03/2024 08:59:05

N.B. To customers, Authorised Agents, Representatives, or responsible persons signing this delivery ticket. This is in your interest - Please read this ticket fully and inspect material, agreeing quantity, quality and everything is to your satisfaction before finally signing the receipt note.

We regret we cannot under any circumstances entertain any claims concerning quantity or quality once the vehicle has left the site and a clear signature has been given.

Received by:

Will

WILL

Driver :

KARL BIGGINGTON

Customer ordering vehicles off the public road do so entirely at their own responsibility . we cannot accept responsibility for damage caused by our vehicles while driving to your site.

All materials supplied will remain the property of Britaniacrest Recycling Ltd until paid for in full.

All materials collected remain the property of the customer until paid for in full.

Both are executed or sold subject to Britaniacrest Recycling Ltd's Conditions of Trading.



BIFFA WASTE SERVICES LIMITED
CORONATION ROAD, CRESSEX
HIGH WYCOMBE
BUCKS. HP12 3TZ

VAT No. 537 9116 27 Company Reg. No. 946107

Landfill Tax no. XFLF00000100123 (Eng. & N.I.) and Landfill Disposal Tax no. 379001 (Wales)

TELEPHONE: 01494 521221

FACSIMILE: 01494 463368

ITE 933 REOHILL LANDFILL SITE

C. No. BU9126
CENSING AUTHORITY Thames - South East

CENCE HOLDER BIFFA WASTE SERVICES 7833

USTOMER BRITANNIACREST RECYCLING
ODE R2133941-87
DDRESS NORTH PARADE
HORSHAM
WEST SUSSEX
RH12 2QR 39.00
OSTCODE BRITANNIACREST RECYCLING LTD
AULIER
ARRIER REG. No. CROU131213
EGISTRATION AUTHORITY
A NATIONAL C.B.C.
GL19FWY BULK ROAD VEHICLES
EHICLE
ONTAINER 14.00
U.M

TICKET N [REDACTED] DATE 21/03/2024

CUSTOMER
TRANSFER NOTE No. 7769647
LOAD REF. MJ00625
ORDER REF HAZ SOIL FOR SNR DISPOSAL
SOURCE W550 Horsham

WASTE DESCRIPTION
(HAZ SOIL) Haz Soil For Snr Disposal
CODE 170503
DESTINATION DIS DISPOSAL
CONTRACT 1503624171
EWC CODE 170503
PRE-TREATED
CONSIGNMENT CODE HYSTAR/00010
LANDFILL TAX EXEMPTION REF. No Standard mate

DEPOSIT THIS LOAD AT 16
PHASE LIFT CELL

	WEIGHT	DATE	TIME	TALLY No.
ROSS	50840 Kg	21/03/2024	08:12	0059275
ARE	13220 Kg	21/03/2024	09:05	0073549
ET	17330 Kg			
TY. CHARGED	*** 17.32 TONNE ***			

THIS IS NOT A VAT INVOICE
NET COST *****
VAT @ ***** % *****
TOTAL COST *****

Y SIGNING THIS WASTE TRANSFER NOTE THE HOLDER / CUSTOMER IS CONFIRMING THAT THEY HAVE FULFILLED THEIR DUTY TO
PLY THE W.F.D. WASTE HIERARCHY.

OR BIFFA WASTE SERVICES

RORY MCCANN

AME

DRIVERS SIGNATURE
FOR

KARL BIGGI

NAME

THIS DOCUMENT IS A WASTE TRANSFER NOTE AS PROVIDED FOR BY ENVIRONMENTAL PROTECTION (DUTY OF CARE) REGULATIONS 1991. A TALLY RECORD OF THIS TRANSACTION IS AVAILABLE FOR 6 MONTHS.
HERE WASTE MATERIALS ARE FOUND ON DISCHARGE TO BE INCONSISTENT WITH THE DESCRIPTION, BIFFA WASTE SERVICES RESERVE THE RIGHT TO RECOVER THE APPROPRIATE CHARGE AND ASSOCIATED
X FROM THE CUSTOMER. BIFFA WASTE SERVICES AS OPERATORS OF THE SITE ARE AUTHORISED BY THE HOLDER OF THE APPROPRIATE PERMIT TO ACCEPT WASTE FOR DISPOSAL.

The Hazardous Waste Regulations 2005: Consignment Note



Environment
Agency

PRODUCER'S/HOLDER'S/CONSIGNOR'S COPY (Delete as appropriate)

PART A Notification details

1 Consignment note code: **HYSTAR100010**

2 The waste described below is to be removed from (name, address, postcode, telephone, e-mail, facsimile):

**HYSTAR GROUP
EX SMITH + WESTERN SITE
NORTH PARADE
HORNHAM RH12 2AR**

3 The waste will be taken to (name, address and postcode):

**BIFFA WASTE SERVICES, PATTERSON COURT
LADHILL, CORMAUGERS LANE, REDHILL
RH1 4ER**

4 The waste producer was (if different from 2) (name, address, postcode, telephone, e-mail, facsimile):

AS A2

PART B Description of the waste

If continuation sheet used, tick here ☐

1 The process giving rise to the waste(s) was:

2 SIC (2007) for the process giving rise to the waste: **43.12.1**

3 WASTE DETAILS (where more than one waste type is collected all of the information given below must be completed for each EWC identified)

Description of waste	List of wastes (EWC code)(6 digits)	Quantity (kg)	The chemical/biological components in the waste and their concentrations are:		Physical form (gas, liquid, solid, powder, sludge or mixed)	Hazard code(s)	Container type, number and size
			Component	Concentration (% or mg/kg)			
SOIL + STONE CONTAINING DANGEROUS SUBSTANCES	170503	20000	TPH	10%	SOLID	H7	13 m³

The information given below is to be completed for each EWC identified

EWC code	UN identification number(s)	Proper shipping name(s)	UN class(es)	Packing group(s)	Special handling requirements
170503					APPROPRIATE PPE

PART C Carrier's certificate

(If more than one carrier is used, please attach schedule for subsequent carriers. If schedule of carriers is attached tick here. ☐)

I certify that I today collected the consignment and that the details in A2, A3 and B3 are correct and I have been advised of any specific handling requirements.

Where this note comprises part of a multiple collection the round number and collection number are:

1

1 Carrier name: **BRITANNIA CREST RECYCLING LTD**

On behalf of (name, address, postcode, telephone, e-mail, facsimile):

26 REIGATE ROAD, WANDSWORTH LONDON

2 Carrier registration no./reason for exemption: **CB00131214**

3 Vehicle **[REDACTED]** mode of transport, if not road: **GL19FWY**

Signature

Date **21032024** Time **14:40**

PART D Consignor's certificate

I certify that the information in A, B and C has been completed and is correct, that the carrier is registered or exempt and was advised of the appropriate precautionary measures. All of the waste is packaged and labelled correctly and the carrier has been advised of any special handling requirements.

I confirm that I have fulfilled my duty to apply the waste hierarchy as required by Regulation 12 of the Waste (England and Wales) Regulations 2011.

1 Consignor name:

On behalf of (name, address, postcode, telephone, e-mail, facsimile):

AS A4

Signature

Date **21032024** Time **14:40**

PART E Consignee's certificate (where more than one waste type is collected all of the information given below must be completed for each EWC)

Individual EWC code(s) received	Quantity of each EWC code received (kg)	EWC code accepted/rejected	Waste management operation (R or D code)
170503	17320	A/C	DOS

1 I received this waste at the address given in A3 on: Date **21032024** Time **14:40**

2 Vehicle registration no. (or mode of transport if not road): **GL19FWY**

3 Where waste is rejected please provide details:

I certify that waste permit/

authorises the management of the waste described in B at the address given in A3.

Where the consignment forms part of a multiple collection, as identified in Part C, I certify that the total number of consignments forming the collection are:

Name:

On behalf of (name, address, postcode, telephone, e-mail, facsimile):

Signature

Date **21032024** Time **14:40**

