**Discharge of Pre-Occupation Conditions 3 and 4**

**3.** Photo evidence is attached showing the car parking to be retained at all times.

**4.** Scan of invoice from Graf UK is attached indicating purchase of a 22,000 litre rainwater harvesting tank and associated equipment.

Also attached, photo evidence of installation of the system and water efficiency measures, numbered as follows:

1 Tank excavation and placement

2 Tank installed and backfilled

3 Filter assembly and pipework connections to new and existing buildings

4 Rainwater collection from west side roof of new building

5Inside new building - new WC facilities

6 New WC facilities - motion operated urinal, dual flush toilet and wash basin with connections to harvested rainwater

7 Connections to harvested rainwater and mains connection to backup box

8 Tap for washing down outside new building

9 Rainwater collection from east side of building A

10 Supply pipe carrying harvested rainwater to existing WC and tap for washing down

11 Existing WC facility

Note that the washing down tap, originally to be sited at building A has been replaced by those outside the existing WC (10) and outside the new building (8) and that the supply to the pig-housing is no longer in use with consequent savings of mains water.