



05/12/2025 10:36



Code	Observation	Rem
MH	Start node, manhole, reference: FW1	
WL	Water level, 20% of the vertical dimension	
LR	Line deviates right	
RM	Roots, mass, 100% cross-sectional area loss	
SA	Survey abandoned	Ur

