

WF3 (Outside)



WF4 (outside)



WF5 (outside)



WF3 (inside)



WF4 (inside)



WF5 (inside)



WF4 (inside) with close view of WF3 (outside)

WF6 sash window showing deterioration of timber















Existing Inglenook fireplace in sitting room



Existing Inglenook fireplace in sitting room



Example of proposed logburning stove in sitting room



Existing Inglenook fireplace in bedroom 1



Example of proposed fire insert in bedroom 1

Sara Rudkin RIBA Architect
5 Thornden Cowfold Horsham West Sussex, RH13 8AG **Tel: 01403 864 530.**
e-mail: sararudkin@btinternet.com www.sararudkin.co.uk

Revisions:

Original size A2

Title of project: Replacement windows and doors

Title: Photographs of First floor windows and Fireplaces to be replaced.

Client: Mr and Mrs Dowman
Location: Fossbrooks Stane Street Billinghurst RH14 9ET

This drawing is Copyright: Refer to Architect concerning Licence for use.

Date: March **2025** Drawn : **SER** Scale(s): **NTS**

Drawing No: **Fossbrooks/25/05**