GEA
www.gea-ltd.co.uk
Herts | 01727 824666 Notts | 01509 674888

Gas Monitoring

Site	Harwoods Cars - Bentley Site, London Road, Pulborough RH20 1AR	**Job Number** J23187
Client	Harwoods Ltd	**Sheet** 1/1
Engineer	Mason Navarro Pledge	

Date	24/08/2023
Air Temperature °C	19
Barometric Pressure (mB)	1010
Visit No	1

Borehole No	BH1	BH2	BH4	BH7	BH9	
Standpipe Depth	2.9	0.72	3.00	2.21	2.1	
Condition of Standpipe	Good	Good	Good	Good	Good	
Combustible gas (CH4) % LEL	0.0	0.0	0.0	0.0	0.0	
Combustible gas (CH4) % vol	0.0	0.0	0.0	0.0	0.0	
Carbon Dioxide (CO2) % vol	0.1	0.4	0.2	0.1	0.0	
Oxygen (O2) % vol	20.8	20.5	20.3	21.0	20.4	
Hydrogen ppm	0.0	0.0	0.0	0.0	0.0	
Carbon Monoxide ppm	0.0	0.0	0.0	0.0	0.0	
Hydrogen Sulphide (H2S) ppm	0.0	0.0	0.0	0.0	0.0	
Flow Rate (max) l/hr	0.0	0.0	0.0	0.0	0.0	
Relative Downhole Pressure mb	0	0	0	0	0	
Downhole Temperature °C	-	-	-	-	-	
Water Level m	0.22	0.53	0.47	0.55	0.40	
Remarks	PID - 0.0	PID - 0.1	PID - 0.0	PID - 0.1	PID - 0.0	

GEA
www.gea-ltd.co.uk
Herts | 01727 824666 Notts | 01509 674888

Gas Monitoring

Site	Harwoods Cars - Bentley Site, London Road, Pulborough RH20 1AR	**Job Number** J23187
Client	Harwoods Ltd	**Sheet** 1/1
Engineer	Mason Navarro Pledge	

Date	01/09/2023
Air Temperature °C	18
Barometric Pressure (mB)	1014
Visit No	2

Borehole No	BH1	BH2	BH4	BH7	BH9	
Standpipe Depth	2.9	No Access	2.9	2.18	No Access	
Condition of Standpipe	Good		Good	Good		
Combustible gas (CH4) % LEL	0.0		0.0	0.0		
Combustible gas (CH4) % vol	0.0		0.0	0.0		
Carbon Dioxide (CO2) % vol	0.1		0.0	0.0		
Oxygen (O2) % vol	20.3		20.1	21.0		
Hydrogen ppm	0.0		0.0	0.0		
Carbon Monoxide ppm	0.0		0.0	0.0		
Hydrogen Sulphide (H2S) ppm	0.0		0.0	0.0		
Flow Rate (max) l/hr	0.0		0.0	0.0		
Relative Downhole Pressure mb	0		0	0		
Downhole Temperature °C	-		-	-		
Water Level m	0.30		0.50	0.53		
Remarks	PID - 0.0		PID - 0.0	PID - 0.1		

GEA

www.gea-ltd.co.uk

Herts | 01727 824666 Notts | 01509 674888

Gas Monitoring

Site	Harwoods Cars - Bentley Site, London Road, Pulborough RH20 1AR
Client	Harwoods Ltd
Engineer	Mason Navarro Pledge

Job Number J23187

Sheet 1/1

Date	02/02/2024
Air Temperature °C	12
Barometric Pressure (mB)	1031
Visit No	3

Borehole No	BH1	BH2	BH4	BH7	BH9	
Standpipe Depth	2.9	0.72	No Access	2.18	2.22	
Condition of Standpipe	Good	Good		Good	Good	
Combustible gas (CH4) % LEL	0	0		0	0	
Combustible gas (CH4) % vol	0	0		0	0	
Carbon Dioxide (CO2) % vol	0	0.2		0	0.1	
Oxygen (O2) % vol	19.8	19.2		20.1	20.2	
Hydrogen ppm	0	0		0	0	
Carbon Monoxide ppm	0	0		0	0	
Hydrogen Sulphide (H2S) ppm	0	0		0	0	
Flow Rate (max) l/hr	0	0		0	0	
Relative Downhole Pressure mb	0	0		0	0	
Downhole Temperature °C	NR	NR		NR	NR	
Water Level m	0.2	0.54		0.5	0.45	
Remarks	PID: 0.0	PID: 0.0		PID: 0.1	PID: 0.0	

GEA

www.gea-ltd.co.uk

Herts | 01727 824666 Notts | 01509 674888

Gas Monitoring

Site	Harwoods Cars - Bentley Site, London Road, Pulborough RH20 1AR	**Job Number** J23187
Client	Harwoods Ltd	**Sheet** 1/1
Engineer	Mason Navarro Pledge	

Date	06/02/2024
Air Temperature °C	12
Barometric Pressure (mB)	1012
Visit No	4

Borehole No	BH1	BH2	BH4	BH7	BH9	
Standpipe Depth	3.13	0.7	No Access	2.21	2.1	
Condition of Standpipe	Good	Good		Good	Good	
Combustible gas (CH4) % LEL	0	0		0	0	
Combustible gas (CH4) % vol	0	0		0	0	
Carbon Dioxide (CO2) % vol	0	0		0.1	0	
Oxygen (O2) % vol	20.4	20.5		20.4	20.4	
Hydrogen ppm	0	0		0	0	
Carbon Monoxide ppm	0	0		0	0	
Hydrogen Sulphide (H2S) ppm	0	0		0	0	
Flow Rate (max) l/hr	0	0		0	0	
Relative Downhole Pressure mb	0	0		0	0	
Downhole Temperature °C	NR	NR		NR	NR	
Water Level m	0.26	0.56		0.53	0.5	
Remarks	PID: 0.0	PID: 0.0		PID: 0.2	PID: 0.1	