


Elevation 1

vertical tiling to be repaired / replaced as per roofing quote s.of w.

cracks to render to be repaired and made good

existing SVP



2 no side elevation windows to be replaced with more traditional profiles

Elevation 2

Scale Bar (meters)

0 5 10 15 20

Rev A: note re side elev windows added 18.10.2024

NOTES
SURVEY IS BASED ON OS GRID SYSTEM ORIGINATING FROM STATION 1
@ E 517482.042, N 111293.474, RL 19.740

Control Stations

Elevation

Client: Jaye Ford

Drawing Title: Elevations

Job Title: Box House, 75 High Street Steyning, BN44 3RE

LBC PROPOSALS

Scale	Date	Drawn	Job No.	Drawing No.	Rev
1:100@A3	19/08/24	DH/CH	004 08 24	2991/0014	A
	Surveyed by AR	Checked SE			