



Asset:

Church lane Grill AD-T-049 [532934]

**Inspection Id:

APSRAT2500258

Inspection Unit: Adur-Tre...D 37083)

Honeypot site:



**Inspection Type: PSRA Tree

**Inspected By:



**Schedule Date:



06/04/2026

Date Started:



24/03/2026 10:01

Comments:

Tree work is required for removal of the small tree dead/dying leaning across the channel in front of the trash screen and removal of the J-curve limb growing from mature Ash tree, the limb is growing out towards the public footpath. There is a small amount of lvy growing on the tree nearest to the screen.

Location Description:

Key / Access
Card Required:

No

Landowner
Contact Required:

No