

Holbrook Surgery – Context Photographs

Note: All photos taken on 12th May 2026 unless otherwise stated



Photo 1 – Front (East) Elevation



Photo 2 – Side (North) Elevation and location of extension



Photo 3 – South Elevation – Extension not visible – Image dated June 2024 ©Google



Photo 4/5 – Rear (West) elevation. Whole elevation cannot be photographed due to site constraints and location of boundary



Photo 6 – Site of proposed extension. Note adjacent property at 20 Highdown View just visible through trees



Photo 7 – View from Highdown Way towards site – Note window to first floor at rear of No.20 (to LSH)



Photo 8 – View from rear of Holbrook Surgery showing No. 21 Highdown View. Small First floor window just visible through trees

Cont...



Photo 9 – Google Image showing context view from North – Note No.21 Highdown View has a single first floor window in the gable, with trees screening the site ©Google



Photo 10 – Google Image showing context view from East – Note both 20 & 21 Highdown View and first floor window positions indicated but both heavily screened by trees and planting ©Google



Photo 11 - Google Image showing context view from South – Note 20 Highdown View first floor window positions indicated but heavily screened by trees and planting ©Google

