21 Broomfield Drive:


1



2



3



4



Details:

1 - the rear of the house with the conservatory.

2 - the conservatory has been knocked down (block and beam flooring has been put in) and foundations for brick extension have been put in.

3 - map of the house and garden. The blue outline shows where the conservatory was positioned and where we would like extension.

4 - Ariel view from google earth shows the conservatory's position.